

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 22192Main Street: MOORELAND_FARMS_RDCross Street: CARMEL_RDLocation:SADA ID: 69DB81EE38DFRamp Type: PerpDiagInitial Pass/Fail: FailOverall Compliance: NoSeverity Score: 13.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

MOORELAND FARMS RD StopSign CARMEL RD

None

Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.2.2, R304.5.3

Total Cost: \$ 3200.00

Field Measurements/Component Compliance							
	Comp	liance Description	Data	Comp	liance De	scription	Data
	N/A	Ramp Length (in)	48.0	No	Ramp Slo	ppe (%)	9.1
	Yes	Ramp Width (in)	48.0	No	Ramp XS	lope (%)	3.3
	N/A	Flare Type LT	N/A	N/A	Flare Typ	e RT	N/A
	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slop	pe RT (%)	N/A
	N/A	Flare Traversable LT?	N/A	N/A	Flare Trav	versable RT?	N/A
	N/A	Landing Length (in)	N/A	N/A	DWS Pro	vided?	N/A
	N/A	Landing Width (in)	N/A	N/A	DWS Cor	ntrast?	N/A
	N/A	Landing Slope (%)	N/A	N/A	DWS Len	igth (in)	N/A
	N/A	Landing X Slope (%)	N/A	N/A	DWS Full	Width?	N/A
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offs	set (in)	N/A
	N/A	Shared Landing?	N/A				
	N/A	Gutter Ponding?	N/A	N/A	Gutter Slo	ope (%)	N/A
	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X	Slope (%)	N/A
	N/A	Painted X Walk1?	No	N/A	Painted X	Walk2?	No
		X Walk 1 Direction	To NE		X Walk 2	Direction	To NW
	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2	Width (in)	N/A
		X Walk 1 Slope (%)	1.2		X Walk 2	Slope (%)	4.3
		X Walk 1 X Slope (%)	3.5		X Walk 2	X Slope (%)	1.9
	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp ins	ide XWalk2?	N/A
		Road Slope (%)	1.7	N/A	Clear Spa	ace?	N/A
		Road X Slope (%)	4.9	N/A	Clear Spa	ace to XWalk (in)	N/A
	N/A	Any Obstructions?	N/A	N/A	Storm Gra	ate/Utility Hazard?	N/A
		Obstruction Type			Storm Gra	ate/Utility Type	
			N/A				N/A
				Yes	Surface C	Condition? (G/P)	Good
	. W	-1		-			





