

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 18932 Ma	ain Street: GLENHAM_DR	Cross Street	: TYVOLA_RD		Location:	SW
	amp Type: Perp	Initial Pass/Fail: Fail Overall Compliance: No			No Severity Score:	33.75
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance				
the best for	Possible Solutions:			ompliance Description	Data	
	Remove & Replace Entire Ramp		Ramp Length (in)	65.0 No		12.4
		No	Ramp Width (in)	40.0 Yes		1.3
E Contraction of the contraction	11	N/A	Flare Type LT	N/A N/A	A Flare Type RT	N/A
		N/A	Flare Slope LT (%)	N/A N/A	••	N/A
		N/A	Flare Traversable LT?	N/A N/A	A Flare Traversable RT?	N/A
Tryola		N/A	Landing Length (in)	N/A N/A	A DWS Provided?	N/A
Contraction of the second seco	Surveyor Notes:	N/A	Landing Width (in)	N/A N/A	A DWS Contrast?	N/A
Collection of the second	N/A	N/A	Landing Slope (%)	N/A N/A	A DWS Length (in)	N/A
A A A A A A A A A A A A A A A A A A A	Eline.	N/A	Landing X Slope (%)	N/A N/A	A DWS Full Width?	N/A
		N/A	Landing Curb? (Y/N)	N/A N/A	A DWS Offset (in)	N/A
		N/A	Shared Landing?	N/A		
A State of the sta	PROW/ADA:	N/A	Gutter Ponding?	N/A N/A	A Gutter Slope (%)	N/A
I and the second second	Not Found, R304.5.1, R304.2.2	N/A	Gutter Lip Ht (in)	N/A N/A	,	N/A
		N/A	Painted X Walk1?	No N/A	A Painted X Walk2?	N/A
			X Walk 1 Direction	To N	X Walk 2 Direction	N/A
		N/A	X Walk 1 Width (in)	N/A N/A	A X Walk 2 Width (in)	N/A
Street 1 Name TYVOL	A RD		X Walk 1 Slope (%)	5.8	X Walk 2 Slope (%)	N/A
	None		X Walk 1 X Slope (%)	0.2	X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A	N/A	Ramp inside XWalk1?	N/A N/A	A Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A		Road Slope (%)	N/A N/A	A Clear Space?	N/A
			Road X Slope (%)	N/A N/A	•	N/A
		N/A	Any Obstructions?	N/A N/A	,	N/A
	Total Cost: \$	1850.00	Obstruction Type		Storm Grate/Utility Type	
				N/A		N/A