

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

12.2

3.4

N/A

Intersection ID: 13916 Main Street: CLANTON RD **Cross Street: WEST BV** Location: NW Initial Pass/Fail: Fail **Overall Compliance: No** ADA ID: 6AC2D0A9A6C6 Ramp Type: Perp Severity Score: 26.25

Compliance Description

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Flare Traversable LT?

Flare Type LT

N/A

Yes

N/A

N/A

N/A

N/A

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance Data

60.0

60.0

N/A

Yes

To S

108.0

0.9

4.8

Yes

N/A

No

Yes

N/A

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space?

Flare Traversable RT?




WEST BV Street 1 Name Stop Condition-Street 2 Signal N/A Street 2 Name Stop Condition-Street 1 N/A

1 COCIDIO COIGNON					
Possible Solutions:					
Remove & Replace Entire Ramp.					
Cumusuum Natara					
Surveyor Notes:					
N/A					
PROW/ADA:					
R304.2.2					
TOO TIELE					

s:		N/A	Landing Width (in)
		N/A	Landing Slope (%)
		N/A	Landing X Slope (%)
		N/A	Landing Curb? (Y/N)
		N/A	Shared Landing?
		N/A	Gutter Ponding?
		N/A	Gutter Lip Ht (in)
		N/A	Painted X Walk1?
			X Walk 1 Direction
		N/A	X Walk 1 Width (in)
			X Walk 1 Slope (%)
			X Walk 1 X Slope (%)
		N/A	Ramp inside XWalk1?
			Road Slope (%)
			Road X Slope (%)
		N/A	Any Obstructions?
	\$ 1850.00		Obstruction Type









Total Cost: