


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 52449	Main Street: TRANQUIL_OAK_PL	Cross Street: PAT_GARRETT_ST	Location: SE
ADA ID: 6AEB76A3A09C	Ramp Type: Directional1	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 25	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance											
<div></div> <div>Street 1 Name<div>TRANQUIL OAK PL</div></div> <div>Stop Condition-Street 1<div>StopSign</div></div> <div>Street 2 Name<div>N/A</div></div> <div>Stop Condition-Street 2<div>N/A</div></div>			Possible Solutions:			Compliance			Description			Data		
			Remove & Replace Entire Ramp.			N/A			Ramp Length (in)			82.0		
						Yes			Ramp Width (in)			67.0		
						No			Ramp Slope (%)			12.8		
						Yes			Ramp XSlope (%)			0.2		
						N/A			Flare Type LT			N/A		
						N/A			Flare Slope LT (%)			N/A		
						N/A			Flare Traversable LT?			N/A		
						N/A			Landing Length (in)			0.0		
						N/A			Landing Width (in)			0.0		
						N/A			Landing Slope (%)			0.0		
						N/A			Landing X Slope (%)			0.0		
						N/A			Landing Curb? (Y/N)			N/A		
						N/A			Shared Landing?			N/A		
						N/A			Gutter Ponding?			0.0		
						N/A			Gutter Lip Ht (in)			1.0		
						N/A			Painted X Walk1?			No		
									X Walk 1 Direction			To W		
									X Walk 1 Width (in)			N/A		
									X Walk 1 Slope (%)			2.1		
									X Walk 1 X Slope (%)			0.7		
						N/A			Ramp inside XWalk1?			N/A		
						N/A			Any Obstructions?			N/A		
									Obstruction Type			Yes		
												N/A		
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					
									N/A					

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

R304.2.2

Total Cost:

\$ 1600.00

