

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 6932 Main Stu	reet: OLD_MT_HOLLY_RD	Cross Street	: WEST AV		Location:	Е
			Initial Pass/Fail: Fail Overall Complia			
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance				
Possible Solutions:		Compliance Description Data Compliance Description Data				
			Ramp Length (in)	57.0 Yes		5.1
FERRY NO	Remove & Replace Entire Ramp.	No	Ramp Width (in)	47.5 No	Ramp XSlope (%)	7.6
COURSE AND AND AND		N/A	Flare Type LT	N/A N/A	,	7.0 N/A
Non the part of the state of the		N/A	Flare Slope LT (%)	N/A N/A	51	N/A
OLD_INT_FOLDY_FD 6		N/A	Flare Traversable LT?	N/A N/A	1 ( )	N/A
	-	N/A N/A	Landing Length (in)	N/A N/A		N/A N/A
	Surveyor Notes:	N/A	Landing Width (in)			N/A
		N/A	Landing Slope (%)	N/A N/A		N/A
	N/A		••••			
		N/A	Landing X Slope (%)	N/A N/A		N/A
		N/A	Landing Curb? (Y/N)	N/A N/A	DWS Offset (in)	N/A
		N/A	Shared Landing?	N/A		
	PROW/ADA:	N/A	Gutter Ponding?	N/A N/A	Gutter Slope (%)	N/A
THE AVERT PLANT AND	Not Found, R304.5.1, R304.5.3	N/A	Gutter Lip Ht (in)	N/A N/A	Gutter X Slope (%)	N/A
		N/A	Painted X Walk1?	No N/A	Painted X Walk2?	N/A
· · · · · · · · · · · · · · · · · · ·			X Walk 1 Direction	To W	X Walk 2 Direction	N/A
		N/A	X Walk 1 Width (in)	N/A N/A	X Walk 2 Width (in)	N/A
Street 1 Name WEST AV			X Walk 1 Slope (%)	2.5	X Walk 2 Slope (%)	N/A
Stop Condition-Street 2 StopSign			X Walk 1 X Slope (%)	4.8	X Walk 2 X Slope (%)	N/A
Street 2 Name N/A		N/A	Ramp inside XWalk1?	N/A N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1 N/A			Road Slope (%)	4.8 N/A	Clear Space?	N/A
			Road X Slope (%)	2.5 N/A	•	N/A
		N/A	Any Obstructions?	N/A N/A	- 1 (7	N/A
	Total Cost: \$ 1	850.00	Obstruction Type		Storm Grate/Utility Type	
	•		,,	N/A		N/A

**Yes** Surface Condition? (G/P)

Good

