cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



| Intersection ID: 31777 | Main Street: MOCKERNUT_DR | | | et: | PINYON_PINE_LN | Location: | SE | | | |
|---|---------------------------|--|--------|---|-----------------------|---------------|-------------------|-----------------------------|------|--|
| ADA ID: 6E16D02E752C | Ramp Ty | Initial Pass/Fail: Fail Overall Compliance: No | | | | | o Severity Score: | 8.75 | | |
| Codes/Mitigation Info/Possible Solution | | | | Field Measurements/Component Compliance | | | | | | |
| E T | PUTRON FUTA LAN | Possible Solutions: | Co | Compliance Description | | Data Complian | | nce Description | Data | |
| COLLET TILLET | | Remove & Replace Curb Ramp W | ith N/ | Α | Ramp Length (in) | 82.5 | Yes | Ramp Slope (%) | 5.7 | |
| | | Two New Directional Ramps or | No | c | Ramp Width (in) | 44.0 | Yes | Ramp XSlope (%) | 2.0 | |
| | | Equivalent. | N// | Α | Flare Type LT | N/A | N/A | Flare Type RT | N/A | |
| | | | N// | A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A | |
| | | | N// | A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A | |
| B. C. P | | | N// | A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A | |
| | | Surveyor Notes: | N// | A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A | |
| | | N/A | N// | A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A | |
| | | | N// | A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A | |
| | | | N// | A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A | |
| FUL OT C. S. | | N// | A | Shared Landing? | N/A | | | | | |
| SCOTICE & | LO I | PROW/ADA: | N// | A | Gutter Ponding? | Yes | N/A | Gutter Slope (%) | N/A | |
| | CAEON | Not Found, R304.5.1 | N// | | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A | |
| Not Found, 1004.5.1 | | | N/ | | Painted X Walk1? | No | | Painted X Walk2? | No | |
| | | | | | X Walk 1 Direction | To NE | | X Walk 2 Direction | To W | |
| | | | N// | A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A | |
| Street 1 Name | PINYON PINE LN | | | | X Walk 1 Slope (%) | 0.4 | | X Walk 2 Slope (%) | 3.5 | |
| Stop Condition-Street 2 | StopSign | | | | X Walk 1 X Slope (%) | 1.8 | | X Walk 2 X Slope (%) | 0.7 | |
| Street 2 Name | MOCKERNUT DR | | N// | Δ | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A | |
| Stop Condition-Street 1 | None | | | | Road Slope (%) | 0.2 | | Clear Space? | N/A | |
| | | | | | Road X Slope (%) | 1.6 | N/A | Clear Space to XWalk (in) | N/A | |
| | | | N/ | Α | Any Obstructions? | N/A | | Storm Grate/Utility Hazard? | N/A | |
| | | Total Cost: \$ 32 | 00.00 | - • | Obstruction Type | | | Storm Grate/Utility Type | | |
| 1 | | | | | | N/A | | | N/A | |
| 1 | | | | | | 13/A | 1 | | 11/1 | |

Yes Surface Condition? (G/P)

Good





