

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 25776	Main Sti	Main Street: CARMEL_COMMONS_BV				PINEVILLE-MATTHEW	Location:	SW			
ADA ID: 6F193BD9699	A Ramp T	Ramp Type: IslandPerp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	22.5	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
	A	Possible Solutions:		Compliance Description				Data Compliance Description			
0		Remove & Replace Entire	ntire Ramp.		N/A	Ramp Length (in)	50.0	No	Ramp Slope (%)	10.2	
1710 W.					No	Ramp Width (in)	43.0	No	Ramp XSlope (%)	3.0	
M. K. W. M.					N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
The second s	<b>\$</b>				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
PINEVILLE-MATTHEWS RD					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
the like		Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
B - fate	N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
6. 9					N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
and the second second					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
					N/A	Shared Landing?	N/A				
		PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	Star 2 1	Not Found, R304.5.1	. R304.2.2.		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
NEG DEC		R304.5.3	, ,		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
The second s	A Start					X Walk 1 Direction	To E		X Walk 2 Direction	N/A	
					N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	CARMEL COMMONS BV					X Walk 1 Slope (%)	1.8		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	StopSign					X Walk 1 X Slope (%)	1.7		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A	
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost:	\$3	400.00		Obstruction Type			Storm Grate/Utility Type		
							N/A			N/A	

s Surface Condition? (G/P)

Good

