


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 48243	Main Street: YELLOWSTONE SPRINGS LN	Cross Street: NORMANS LANDING DR	Location: NE
ADA ID: 6F6830357A94	Ramp Type: BlendTrans1	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 42.5	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
 <p>Street 1 Name YELLOWSTON SPRINGS LN</p> <p>Stop Condition-Street 1 None</p> <p>Street 2 Name NORMANS LANDING DR</p> <p>Stop Condition-Street 2 None</p>	Possible Solutions:		Compliance	Description	Data	Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		N/A	Ramp Length (in)	48.0	Yes	BlendTrans Slope (%)	4.6
			No	Ramp Width (in)	34.5	No	BlendTrans XSlope (%)	8.0
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	N/A
		N/A	Shared Landing?	N/A				
		N/A	Gutter Ponding?	N/A	N/A	N/A	Gutter Slope (%)	N/A
		N/A	Gutter Lip Ht (in)	N/A	N/A	N/A	Gutter X Slope (%)	N/A
		N/A	Painted X Walk1?	No	N/A	N/A	Painted X Walk2?	No
			X Walk 1 Direction	To W			X Walk 2 Direction	To S
			X Walk 1 Width (in)	N/A			X Walk 2 Width (in)	N/A
			X Walk 1 Slope (%)	5.3			X Walk 2 Slope (%)	2.6
			X Walk 1 X Slope (%)	2.6			X Walk 2 X Slope (%)	4.9
		N/A	Ramp inside XWalk1?	N/A	N/A	N/A	Ramp inside XWalk2?	N/A
			Road Slope (%)	3.0			Clear Space?	N/A
			Road X Slope (%)	2.0	N/A	N/A	Clear Space to XWalk (in)	N/A
		N/A	Any Obstructions?	N/A	N/A	N/A	Storm Grate/Utility Hazard?	N/A
			Obstruction Type				Storm Grate/Utility Type	
					N/A			N/A
						Yes	Surface Condition? (G/P)	Good
						No	Curb Slope (%)	8.2
Surveyor Notes:								
N/A								
PROW/ADA:								
Not Found, R304.5.1, R304.5.3								
Total Cost:		\$	3200.00					

