cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A

Curb Slope (%)

4.9

Intersection ID: 17843	Main Street: E_WOODLAWN_RD			Street:	GILMORE_DR	Location:	SW		
ADA ID: 7002D58B05B4	Ramp Ty	Ramp Type: ParaDiag			Initial Pass/Fail: Fail Overall Compliance: No				13.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
64	6	Possible Solutions:		Compliance Description			Data Compliance Description		Data
		Remove & Replace Curb Ram	n With	N/A	Ramp Length LT (in)	57.0	N/A	Ramp Length RT (in)	52.0
		Two New Directional Ramps of	•	Yes	Ramp Width LT (in)	82.0	Yes	Ramp Width RT (in)	71.0
		Equivalent.		Yes	Ramp Slope LT (%)	0.1	No	Ramp Slope RT (%)	8.8
				No	Ramp XSlope LT (%)	3.0	Yes	Ramp XSlope RT (%)	0.4
S Moon				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
and the second				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
- Maradi	400	Surveyor Notes:		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
E.		LT RP < 5%		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
		LI RF < 5%		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	6			N/A	Shared Landing?	N/A		DWS Oliset (III)	11/2
Sec. St	1 1 1 1 1 1			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
A CAN SI	- Ital	PROW/ADA:		N/A	6		N/A	,	N/A N/A
	Provent in				Gutter Lip Ht (in)	1.0		Gutter X Slope (%)	
	A	R304.5.3, R304.3.2		N/A	Painted X Walk1?	No T of	N/A	Painted X Walk2?	No
and any financial					X Walk 1 Direction	To SE		X Walk 2 Direction	To NE
The second	STA JAN			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
					X Walk 1 Slope (%)	4.8		X Walk 2 Slope (%)	3.0
Street 1 Name	GILMORE DR				X Walk 1 X Slope (%)	4.8		X Walk 2 X Slope (%)	1.2
Stop Condition-Street 1	StopSign			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Street 2 Name	E WOODLAWN RD				Road Slope (%)	2.4	N/A	Clear Space?	N/A
Stop Condition-Street 2	None				Road X Slope (%)	9.0	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
					Obstruction Type			Storm Grate/Utility Type	
		Total Cost: \$	3200.00			N/A			N/A
1							Yes	Surface Condition? (G/P)	Good

