

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

5.0

3.1

0.0

Yes

Yes

Yes

24.0

Yes

0.0

4.7

2.6

N/A

N/A

N/A

N/A

N/A

N/A

Yes

N/A

Sloped

Intersection ID: 5192 Main Street: CARRONBRIDGE LN Cross Street: SOUTHMINSTER LN Location: Ν

Overall Compliance: No Severity Score: ADA ID: 71AF28AEB2B9 Ramp Type: BlendTrans1 Initial Pass/Fail: Pass 7.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Yes

No

N/A

Yes

N/A

Yes

Yes

Yes

Yes

Yes

Yes

Yes

No N/A

Compliance Description

Flare Type RT

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space?

Flare Traversable RT?

BlendTrans Slope (%)

BlendTrans XSlope (%)

Data

24.0

48.0

5.6

Yes

46.0

48.0

1.9

4.2

No

No

No

0.5

N/A

Sloped



SOUTHMINSTER LN Street 1 Name Stop Condition-Street 1 None N/A Street 2 Name Stop Condition-Street 2 N/A Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A


PROW/ADA

Not Found, R304.5.3, R304.2.1, R302.7.2

N/A	Ramp Length (in)		
Yes	Ramp Width (in)		
N/A	Flare Type LT		
Yes	Flare Slope LT (%)		
N/A	Flare Traversable LT?		
No	Landing Length (in)		
Yes	Landing Width (in)		
Yes	Landing Slope (%)		
No	Landing X Slope (%)		
N/A	Landing Curb? (Y/N)		
N/A	Shared Landing?		
Yes	Gutter Ponding?		
No	Gutter Lip Ht (in)		
N/A	Painted X Walk1?		
	X Walk 1 Direction		
	X Walk 1 Width (in)		
	X Walk 1 Slope (%)		
	X Walk 1 X Slope (%)		
N/A	Ramp inside XWalk1?		
	Road Slope (%)		
	Road X Slope (%)		
Yes	Any Obstructions?		

Compliance Description

	X Walk 1 Direction	To S	
	X Walk 1 Width (in)	N/A	
	X Walk 1 Slope (%)	1.9	
	X Walk 1 X Slope (%)	2.7	
	Ramp inside XWalk1?	N/A	N/A
	Road Slope (%)	2.7	
	Road X Slope (%)	1.9	N/A
•	Any Obstructions?	No	Yes
	Obstruction Type		



Clear Space to XWalk (in)





Total Cost:



3200.00