cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 29391 Main Stu	29391 Main Street: FIREFLY_LN		treet:	GOLD_PAN_RD	Location:	N		
ADA ID: 72BD932A5533 Ramp Ty	0: 72BD932A5533 Ramp Type: PerpDiag		ass/Fa	nil: Fail Overall	o Severity Score:	33.75		
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance						
	Possible Solutions:		Compliance Description D			a Compliance Description		Data
	Remove & Replace Curb Ramp W	/ith	N/A	Ramp Length (in)	48.5	No	Ramp Slope (%)	8.7
	Two New Directional Ramps or Equivalent.		No	Ramp Width (in)	47.0	No	Ramp XSlope (%)	5.4
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	N/A			
	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Not Found, R304.5.1, R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
				X Walk 1 Direction	To SW		X Walk 2 Direction	To SE
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name FIREFLY LN				X Walk 1 Slope (%)	1.5		X Walk 2 Slope (%)	2.2
Stop Condition-Street 2 StopSign				X Walk 1 X Slope (%)	0.9		X Walk 2 X Slope (%)	3.4
Street 2 Name GOLD PAN RD			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1 None				Road Slope (%)	6.5	N/A	Clear Space?	N/A
				Road X Slope (%)	0.8	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A

Yes Surface Condition? (G/P)

Good





