

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

10.0

1.3

N/A

Main Street: N TRYON ST Intersection ID: 5468 Cross Street: J W CLAY BV Location: W Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 12.5 ADA ID: 7344145AC063 Ramp Type: Perp

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Yes

Yes

N/A

Compliance Description

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space?

Flare Traversable RT?

Flare Type RT

Data

184.0

48.0

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Yes

1.5

No

N/A

3.0

1.3

N/A

N/A

To NE




J W CLAY BV Street 1 Name Stop Condition-Street 2 Signal N/A Street 2 Name Stop Condition-Street 1 N/A

Possible Solutions:						
Remove & Replace Entire Ramp.						
Remove & Replace Little Ramp.						
Surveyor Notes:						
N/A						
PROW/ADA:						
N/A						

			N/A
			N/A
PROW/ADA:			N/A
N/A			N/A
			N/A
Total Cost:	\$	1850.00	

	Times.		
		A-A	



Compliance Description

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing? **Gutter Ponding?**

Gutter Lip Ht (in)

Painted X Walk1?

X Walk 1 Direction

X Walk 1 Width (in)

X Walk 1 Slope (%)

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road Slope (%)

Flare Traversable LT?

Flare Type LT

N/A

Yes

N/A

N/A

N/A

N/A

N/A

N/A

N/A



