

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

87.0

65.0

9.9

1.7

11.1

4.9

N/A

No

To E

N/A

0.2

6.1

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Good 8.4

Intersection ID: 19071 Main Street: S\_TRYON\_ST Cross Street: LAND\_GRANT\_RD Location: NW
ADA ID: 73573D286951 Ramp Type: Combination2Diag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 0

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 1
Street 2 Name
Stop Condition-Street 2

None
S TRYON ST
StopSign
LAND GRANT RD

Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.


Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.2.2, R304.5.3, R304.3.2

Total Cost:



1.0

N/A

1.8

2.4

N/A

N/A

N/A

N/A

Yes

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

Clear Space?

Any Obstruction?

**Obstruction Type** 


Curb Slope (%)

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road Slope (%)

Road X Slope (%)







N/A

3200.00