## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 23386	Main Street: ALEXANDER_RD			Cross Street: BENNING_WOOD_DR				Location:	SW
ADA ID: 737C1F329291	Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	1.25
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
		Possible Solutions:	Compliance Description Data			Data	Compliance Description		Data
		Remove & Replace Entire Ramp	. N	/ <b>A</b>	Ramp Length (in)	89.0	N/A	Grade Break?	N/A
	5	· · · · · · · · · · · · · · · ·		es	Ramp Width (in)	69.0	N/A	Grade Break Slope (%)	0.0
Ren to the second	Y L	4	Y	es	Ramp Slope (%)	2.2	N/A	Grade Break XSlope (%)	0.0
Parties of the second sec	111		Ν	o	Ramp XSlope (%)	2.6			
	5. M		N	/ <b>A</b>	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	Sea.		Ν	/ <b>A</b>	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
A A A A	2	Surveyor Notes:	Ν	/ <b>A</b>	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	ALL	N/A	Ν	/ <b>A</b>	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
	12		N	/ <b>A</b>	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
	18		N	/ <b>A</b>	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
	1 Cor		Ν	/ <b>A</b>	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
	2 V	PROW/ADA:	Ν	/ <b>A</b>	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
	1	R304.5.3	N	/ <b>A</b>	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
	College 1		Ν	/ <b>A</b>	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
			N	/ <b>A</b>	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
			Ν	/ <b>A</b>	Painted X Walk1?	No		Road Slope (%)	3.3
Street 1 Name MAYS CI	HAPEL LN				X Walk 1 Direction	To NE		Road X Slope (%)	0.6
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A				X Walk 1 Slope (%)	3.3	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	0.6	N/A	Storm Grate/Utility Hazard?	N/A
			Ν	/ <b>A</b>	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
			N	/ <b>A</b>	Any Obstructions?	N/A			N/A
		Total Cost: \$ 1	600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	9.2

