

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 19528 Main Street: SOUTH_BV Cross Street: EMERYWOOD_DR Location: SE

ADA ID: 740A3897E393 Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 22.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Yes

Surface Condition? (G/P)

Good



Street 1 Name	SOUTH BV
Stop Condition-Street 2	Signal
Street 2 Name	N/A
Stop Condition-Street 1	N/A

Possible Solution	Field Measurements/Component Compliance						
Possible Solutions:	Compli	ance Description	Data	Complian	ce Description	Data	
Remove & Replace Entire Ramp.	N/A	Ramp Length (in)	72.0	No R	amp Slope (%)	9.2	
	No	Ramp Width (in)	47.0	Yes Ra	amp XSlope (%)	2.6	
	N/A	Flare Type LT	N/A	N/A FI	are Type RT	N/A	
	N/A	Flare Slope LT (%)	N/A	N/A FI	are Slope RT (%)	N/A	
	N/A	Flare Traversable LT?	N/A	N/A FI	are Traversable RT?	N/A	
	N/A	Landing Length (in)	N/A	N/A D'	WS Provided?	N/A	
Surveyor Notes:	N/A	Landing Width (in)	N/A	N/A D'	WS Contrast?	N/A	
N/A	N/A	Landing Slope (%)	N/A	N/A D'	WS Length (in)	N/A	
	N/A	Landing X Slope (%)	N/A	N/A D'	WS Full Width?	N/A	
	N/A	Landing Curb? (Y/N)	N/A	N/A D'	WS Offset (in)	N/A	
	N/A	Shared Landing?	N/A				
PROW/ADA:	N/A	Gutter Ponding?	N/A	N/A G	utter Slope (%)	N/A	
Not Found, R304.5.1, R304.2.2	N/A	Gutter Lip Ht (in)	N/A	N/A G	utter X Slope (%)	N/A	
	N/A	Painted X Walk1?	Yes	N/A Pa	ainted X Walk2?	N/A	
		X Walk 1 Direction	To W	Х	Walk 2 Direction	N/A	
	N/A	X Walk 1 Width (in)	111.0	N/A X	Walk 2 Width (in)	N/A	
		X Walk 1 Slope (%)	0.9	Х	Walk 2 Slope (%)	N/A	
		X Walk 1 X Slope (%)	3.2	Х	Walk 2 X Slope (%)	N/A	
	N/A	Ramp inside XWalk1?	Yes	N/A R	amp inside XWalk2?	N/A	
		Road Slope (%)	N/A	N/A C	ear Space?	N/A	
		Road X Slope (%)	N/A	N/A C	ear Space to XWalk (in)	N/A	
	N/A	Any Obstructions?	N/A	N/A St	orm Grate/Utility Hazard?	N/A	
Total Cost: \$ 1850.00		Obstruction Type		St	orm Grate/Utility Type		
			N/A			N/A	





