

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Good

Intersection ID: 13263 Main Str	eet: MCCLINTOCK RD	Cross Stree	t: THE_PLAZ	A		Location:	SE
			Initial Pass/Fail: Fail Overall Compliance: No				
							21.20
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance					
	Possible Solutions:	Compliance Description			Data Compliance Description		Data
19	Remove & Replace Entire Ramp.	N/A	Ramp Length		No	Ramp Slope (%)	8.4
		No	Ramp Width (i	in) 46.0	Yes	Ramp XSlope (%)	1.3
The second secon		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		N/A	Flare Slope L	T (%) N/A	N/A	Flare Slope RT (%)	N/A
B. B. B.		N/A	Flare Traversa	able LT? N/A	N/A	Flare Traversable RT?	N/A
The Man		N/A	Landing Lengt	th (in) N/A	N/A	DWS Provided?	N/A
A DOGR	Surveyor Notes:	N/A	Landing Width	n (in) N/A	N/A	DWS Contrast?	N/A
Pit a star	N/A	N/A	Landing Slope	e (%) N/A	N/A	DWS Length (in)	N/A
		N/A	Landing X Slo	pe (%) N/A	N/A	DWS Full Width?	N/A
		N/A	Landing Curb?	? (Y/N) N/A	N/A	DWS Offset (in)	N/A
THE REAL PROPERTY OF		N/A	Shared Landir	ng? N/A			
The second secon	PROW/ADA:	N/A	Gutter Pondin	ng? N/A	N/A	Gutter Slope (%)	N/A
BULLER, S. C. Market Market	Not Found, R304.5.1, R304.2.2	N/A	Gutter Lip Ht ((in) N/A	N/A	Gutter X Slope (%)	N/A
		N/A	Painted X Wal	lk1? Yes	N/A	Painted X Walk2?	N/A
and the second second			X Walk 1 Direc	ction To W		X Walk 2 Direction	N/A
		N/A	X Walk 1 Widt	th (in) 149.0	N/A	X Walk 2 Width (in)	N/A
Street 1 Name THE PLAZA			X Walk 1 Slop	e (%) 4.6		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2 None			X Walk 1 X Slo	ope (%) 2.2		X Walk 2 X Slope (%)	N/A
Street 2 Name N/A		N/A	Ramp inside X	(Walk1? Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1 N/A			Road Slope (%	%) N/A	N/A	Clear Space?	N/A
			Road X Slope	(%) N/A	N/A	Clear Space to XWalk (in)	N/A
		N/A	Any Obstructio		N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$ 1	850.00	Obstruction Ty			Storm Grate/Utility Type	
				N/A			N/A

Yes Surface Condition? (G/P)





