

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

1.5

5.5

N/A

5.0

Good

Intersection ID: 10022060 Main Street: BRYSON_BEND_DR Cross Street: N/A Location: SE

ADA ID: 76AC620C8996 Ramp Type: BlendTrans1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 12.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Yes

No

N/A

Yes

N/A

N/A

Compliance Description

Flare Type RT

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

Clear Space?

Curb Slope (%)

Flare Traversable RT?

BlendTrans Slope (%)

BlendTrans XSlope (%)



Street 1 Name BRYSON BEND DR
Stop Condition-Street 1 None
Street 2 Name N/A
Stop Condition-Street 2 N/A

Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

R304.5.3

N/A

PROW/ADA:
R304.5.3

Total Cost: \$ 3200.00

Compliance Description Data Ramp Length (in) N/A 26.0 48.0 Yes Ramp Width (in) N/A Flare Type LT N/A N/A Flare Slope LT (%) N/A N/A Flare Traversable LT? N/A N/A Landing Length (in) N/A N/A Landing Width (in) N/A N/A N/A Landing Slope (%) N/A Landing X Slope (%) N/A N/A Landing Curb? (Y/N) N/A N/A N/A Shared Landing? N/A **Gutter Ponding?** N/A N/A Gutter Lip Ht (in) N/A N/A Painted X Walk1? No X Walk 1 Direction To NW N/A X Walk 1 Width (in) X Walk 1 Slope (%) 9.1 X Walk 1 X Slope (%) 5.2 N/A N/A Ramp inside XWalk1? Road Slope (%) 5.2 Road X Slope (%) 9.1 N/A N/A Any Obstructions?

Obstruction Type





