


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 10423	Main Street: ACADEMY_ST	Cross Street: E_SUGAR_CREEK_RD	Location: SW
ADA ID: 76B05B78EDA7	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 46.25

Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance			
 <p>Street 1 Name ACADEMY ST</p> <p>Stop Condition-Street 2 StopSign</p> <p>Street 2 Name E SUGAR CREEK RD</p> <p>Stop Condition-Street 1 None</p>	Possible Solutions:	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.			
	Surveyor Notes:	N/A			
	PROW/ADA:	Not Found, R304.5.1, R304.2.2, R304.5.3			
			Compliance	Description	Data
			No	Ramp Length (in)	77.5
			No	Ramp Width (in)	41.0
			N/A	Flare Type LT	N/A
			N/A	Flare Slope LT (%)	N/A
			N/A	Flare Traversable LT?	N/A
			N/A	Landing Length (in)	N/A
			N/A	Landing Width (in)	N/A
			N/A	Landing Slope (%)	N/A
			N/A	Landing X Slope (%)	N/A
			N/A	Landing Curb? (Y/N)	N/A
			N/A	Shared Landing?	N/A
			N/A	Gutter Ponding?	N/A
			N/A	Gutter Lip Ht (in)	N/A
			N/A	Painted X Walk1?	No
			To SE	X Walk 1 Direction	To NE
			N/A	X Walk 1 Width (in)	N/A
			2.5	X Walk 1 Slope (%)	3.0
			2.5	X Walk 1 X Slope (%)	2.8
			N/A	Ramp inside XWalk1?	N/A
			3.3	Road Slope (%)	N/A
			2.5	Road X Slope (%)	N/A
			N/A	Any Obstructions?	N/A
			N/A	Obstruction Type	N/A
			N/A		N/A
			Yes	Surface Condition? (G/P)	Good

Total Cost: \$ 3200.00

