

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Surface Condition? (G/P)

Data

8.5

2.6 N/A

N/A

N/A

N/A

N/A N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A N/A

N/A

N/A

N/A

Good

Intersection ID: 50272 Main Street: SOUTH BV **Cross Street: WHITTON_ST** Location: NE ADA ID: 77C8F2C490DD Ramp Type: Perp Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 22.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name	WHITTON ST
Stop Condition-Street 2	Signal
Street 2 Name	N/A
Stop Condition-Street 1	N/A

i ossibic odiation				T TOTA INTOGOLI	Officer C	ompoi	icht Comphance
Possible Solutions:			Compl	Data	ata Compliance Description		
Remove & Replace Entire	Ram	p.	N/A	Ramp Length (in)	71.5	No	Ramp Slope (%)
•		•	No	Ramp Width (in)	47.0	Yes	Ramp XSlope (%)
			N/A	Flare Type LT	N/A	N/A	Flare Type RT
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?
Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?
N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?
			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)
			N/A	Shared Landing?	N/A		
PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)
Not Found, R304.5.1, R30	4.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)
			N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?
				X Walk 1 Direction	To SW		X Walk 2 Direction
			N/A	X Walk 1 Width (in)	111.0	N/A	X Walk 2 Width (in)
				X Walk 1 Slope (%)	3.0		X Walk 2 Slope (%)
				X Walk 1 X Slope (%)	3.3		X Walk 2 X Slope (%)
			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?
				Road Slope (%)	N/A	N/A	Clear Space?
				Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?
Total Cost:	\$	1850.00		Obstruction Type		l	Storm Grate/Utility Type





