

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



	Main Of		0	04	N1/A			1	NUAZ
Intersection ID: 10025397	7 Main Street: E_ARROWOOD_RD			Street:	N/A	Location:	NW		
ADA ID: 7831621FB0A9 Ramp Type: Directional1			Initial	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
E E	1 . Th-	Possible Solutions:		Compliance Description			Data Compliance Description		Data
		Remove & Replace Entire Ram	р.	N/A	Ramp Length (in)	28.0	N/A	Grade Break?	N/A
30 7 1 1	a la			Yes	Ramp Width (in)	58.0	N/A	Grade Break Slope (%)	0.0
in the second	The la			No	Ramp Slope (%)	13.5	N/A	Grade Break XSlope (%)	0.0
and the second second	NEX V			Yes	Ramp XSlope (%)	0.6			
	· 10 1			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	and the second			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
	NI	Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
en e		N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
E_ARROWOOD_RD	P 41			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
H ANNOLUS	and the second second			N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
and the state of the second	and the second second			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
	P. A.	PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
THE REAL PROPERTY OF THE	A R. M.	R304.2.2		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
				N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
P. Lake & Concert	and the			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
	和"八人"			N/A	Painted X Walk1?	No		Road Slope (%)	9.6
Street 1 Name	ENTRANCE				X Walk 1 Direction	To E		Road X Slope (%)	1.7
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A				X Walk 1 Slope (%)	9.6	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	1.7	N/A	Storm Grate/Utility Hazard?	N/A
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
				N/A	Any Obstructions?	N/A			N/A
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	15.1

