

Access Compliance Report Public Rights-of-Way (Curb Ramps)



| | | • | - | - | | | | | |
|-----------------------------------------|------------------------|------------------------------|---------|------------------------------------------------|-----------------------|-----------|-----------------------------|-----------------------------|-------|
| Intersection ID: 10143 | Main Street: E_34TH_ST | | | Street: | N_DAVIDSON_ST | Location: | S | | |
| ADA ID: 7837A4A29F7B | Ramp Type: PerpDiag | | | Initial Pass/Fail: Fail Overall Compliance: No | | | | o Severity Score: | 12.5 |
| Codes/Mitigation Info/Possible Solution | | | | Field Measurements/Component Compliance | | | | | |
| | | Possible Solutions: | | Compliance Description | | | Data Compliance Description | | Data |
| 0 9 1 | | Remove & Replace Curb Ramp | With | N/A | Ramp Length (in) | 33.0 | No | Ramp Slope (%) | 11.4 |
| 9 - 11 A. M. | | Two New Directional Ramps or | | Yes | Ramp Width (in) | 72.0 | Yes | Ramp XSlope (%) | 1.1 |
| ste se fil | | Equivalent. | | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| 20.99 | | | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| 2 3 5 S | Str. | | | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| | A Start N | | | N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| | A. 2 1 | Surveyor Notes: | | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| | | N/A | | N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| | | | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| | | | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| | | | | N/A | Shared Landing? | N/A | | | |
| | PROW/ADA: | | N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A | |
| | R304.2.2 | | N/A | Gutter Lip Ht (in) | 1.0 | N/A | Gutter X Slope (%) | N/A | |
| | 10041212 | | N/A | Painted X Walk1? | Yes | N/A | Painted X Walk2? | Yes | |
| Market Contraction | | | | | X Walk 1 Direction | To NE | | X Walk 2 Direction | To NW |
| | | | | N/A | X Walk 1 Width (in) | 106.0 | N/A | X Walk 2 Width (in) | 111.0 |
| Street 1 Name | E 34TH ST | | | | X Walk 1 Slope (%) | 2.1 | | X Walk 2 Slope (%) | 4.3 |
| Stop Condition-Street 2 | StopSign | | | | X Walk 1 X Slope (%) | 2.7 | | X Walk 2 X Slope (%) | 0.0 |
| Street 2 Name | N DAVIDSON ST | | | N/A | Ramp inside XWalk1? | Yes | N/A | Ramp inside XWalk2? | Yes |
| Stop Condition-Street 1 | None | | | | Road Slope (%) | 0.1 | N/A | Clear Space? | N/A |
| | | | | | Road X Slope (%) | 3.1 | N/A | Clear Space to XWalk (in) | N/A |
| | | | | N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | | Total Cost: \$ | 3200.00 | | Obstruction Type | | | Storm Grate/Utility Type | |
| | | | | | | N/A | | | N/A |
| | | | | | | | | | |



Good

