

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



					. /						
Intersection ID: 6474	Main Stro	Main Street: CENTURY_OAKS_LN				FALLEN_TREE_CT	Location:		SE		
ADA ID: 79C2CB60024C	Ramp Type: Combination1			Initial	Initial Pass/Fail: Fail Overall Complian			nce: No Severity Score: 46.2		46.25	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
	A MANNER I	Possible Solutions:			Compliance Description		Data Compliance Description			Data	
	and the second second	Remove & Replac	e Entire Ram		N/A	Ramp Length LT (in)	29.0	N/A	Ramp Length RT (in)	48.5	
	A State of the sta			. <b>P</b> .	No	Ramp Width LT (in)	43.0	No	Ramp Width RT (in)	44.0	
					No	Ramp Slope LT (%)	9.5	No	Ramp Slope RT (%)	11.0	
	A MAL				No	Ramp XSlope LT (%)	4.5	No	Ramp XSlope RT (%)	2.9	
	C P Ma				N/A	Ramp Length (in)	49.0	No	Ramp Slope (%)	8.4	
A CARLE	ALLEN TREE OT				No	Ramp Width (in)	36.5	No	Ramp XSlope (%)	11.4	
		Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
		GTR GAP 4.0			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
	Sanda Sanda				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
					N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	STA AND	PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
	- Contraction	Not Found, R304	.5.1, R304.5.1	,	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	to In	R304.2.2, R304.5.	3, R304.3.2		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
	1-1-1				N/A	Shared Landing?	N/A				
					N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
Street 1 Name	Signal				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
Stop Condition-Street 1	FALLEN TREE CT				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
Street 2 Name	N/A					X Walk 1 Direction	To SW		X Walk 2 Direction	N/A	
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
						X Walk 1 Slope (%)	5.8		X Walk 2 Slope (%)	N/A	
						X Walk 1 X Slope (%)	4.0		X Walk 2 X Slope (%)	N/A	
		Total Cost:	\$	1800.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
						Road Slope (%)	N/A		Clear Space?	N/A	
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
Centres OBK								N/A	Any Obstruction?	N/A	
	They be based				and the second				Obstruction Type		
					~					N/A	
			and the second					N/A	Storm Grate/Utility Hazard?	N/A	
					5-				Storm Grate/Utility Type		
1 A A A	Manual A				1	A				N/A	

N/A Surface Condition? (G/P) Good Curb Slope (%) 8.7

Yes