

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

11.1

8.9

N/A

Good

Intersection ID: 43210 Main Street: ENDERLY RD Cross Street: MATHIS DR Location: W Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 55 **ADA ID: 7A1C12707DCE** Ramp Type: Perp

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

No

No

N/A

Yes

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Type

Surface Condition? (G/P)

Storm Grate/Utility Hazard?

Clear Space?

Flare Traversable RT?

Data

125.0

35.0

N/A

No

N/A

4.6

4.4

N/A

N/A

N/A

N/A

N/A

To SE

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

Gutter Ponding?

Gutter Lip Ht (in)

Painted X Walk1?

X Walk 1 Direction

X Walk 1 Width (in)

X Walk 1 Slope (%)

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road Slope (%)

Road X Slope (%)

Any Obstructions?

Obstruction Type

Flare Traversable LT?

Flare Type LT



ENDERLY RD Street 1 Name Stop Condition-Street 2 StopSign N/A Street 2 Name Stop Condition-Street 1 N/A Possible Solutions: Compliance Description N/A Remove & Replace Entire Ramp. No N/A N/A N/A N/A Surveyor Notes: N/A N/A N/A N/A N/A N/A PROW/ADA: N/A Not Found, R304.5.1, R304.2.2, N/A R304.5.3 N/A N/A

Total Cost:



1850.00

N/A

N/A

