

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 3810Main Street: GLASTON_LNCross Street: TAVERNAY_PYLocation:SWADA ID: 7A4E43B3BD4DRamp Type: PerpInitial Pass/Fail: FailOverall Compliance: NoSeverity Score: 12.5

Codes/Mitigation Info/Possible Solution

Total Cost:



Street 1 Name TAVERNAY PY
Stop Condition-Street 2 None
Street 2 Name N/A
Stop Condition-Street 1 N/A

Possible Solutions:	9			
Remove & Replace Entire Ramp.				
•	Y			
	N			
	N			
	N			
	N			
Surveyor Notes:	N			
N/A	N			
	N			
	N			
	N			
PROW/ADA:	N			
Not Found, R304.5.3	N			
	N			
	N			
	N			





1850.00

Field Measurements/Component Compliance								
Compliance Description		Data	Compliance		Description	Data		
N/A	Ramp Length (in)	57.0	Yes	Ramp	Slope (%)	6.2		
Yes	Ramp Width (in)	67.0	No	Ramp	XSlope (%)	6.5		
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A		
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A		
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A		
N/A	Shared Landing?	N/A						
N/A	Gutter Ponding?	N/A	N/A	Gutte	r Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	N/A		
N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?	N/A		
	X Walk 1 Direction	To N		X Wa	lk 2 Direction	N/A		
N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	N/A		
	X Walk 1 Slope (%)	6.1		X Wa	lk 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	2.5		X Wa	lk 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	N/A	N/A	Ram	inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear	Space?	N/A		
	Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storn	n Grate/Utility Hazard?	N/A		
	Obstruction Type			Storn	n Grate/Utility Type			
		N/A				N/A		
			Yes	Surfa	ce Condition? (G/P)	Good		