

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 31813 Main Street: WENDOVER_HILL_CT Cross Street: CHURCHILL_RD Location: NE

ADA ID: 7A70F00D5CF1 Ramp Type: BlendTrans2 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 8.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 1
Street 2 Name
Stop Condition-Street 2

WENDOVER HILL CT StopSign CHURCHILL RD None Possible Solutions:
Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:
ASP LIP 1.0

PROW/ADA:
Not Found, R304.5.1

Total Cost: \$ 3200.00

Compliance Description Data Compliance Description Data Ramp Length (in) Yes BlendTrans Slope (%) N/A 97.0 3.6 Yes No Ramp Width (in) 37.0 BlendTrans XSlope (%) 1.7 N/A N/A Flare Type LT N/A Flare Type RT N/A N/A Flare Slope LT (%) N/A N/A Flare Slope RT (%) N/A N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A Landing Length (in) N/A N/A DWS Provided? N/A N/A Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A N/A N/A Landing Slope (%) DWS Length (in) N/A N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A N/A Shared Landing? N/A **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No N/A Painted X Walk2? No X Walk 1 Direction To W X Walk 2 Direction To S N/A X Walk 1 Width (in) X Walk 2 Width (in) N/A X Walk 1 Slope (%) 1.8 X Walk 2 Slope (%) 2.5 X Walk 1 X Slope (%) 3.2 X Walk 2 X Slope (%) 4.2 N/A N/A Ramp inside XWalk2? N/A N/A Ramp inside XWalk1? Road Slope (%) 0.3 Clear Space? N/A N/A Road X Slope (%) 5.9 Clear Space to XWalk (in) N/A N/A N/A N/A Any Obstructions? Storm Grate/Utility Hazard? N/A **Obstruction Type** Storm Grate/Utility Type N/A N/A Yes Surface Condition? (G/P) Good No 12.3 Curb Slope (%)





