## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



· · · ·											
Intersection ID: 23277	Main Str	Main Street: S_TRYON_ST			Street:	JOHN_PRICE_RD	Location:	NW			
ADA ID: 7B934BA47A55	Ramp Ty	Ramp Type: Perp			Pass/Fa	ail: Pass Overa	o Severity Score:	25.25			
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
		Possible Solutions:			Compliance Description			Data Compliance Description			
S STAN	JOINT LA	Remove & Replace Entire Grind Gutter Lip.	re Ramr	).	N/A	Ramp Length (in)	87.0	Yes	Ramp Slope (%)	7.9	
			•		Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	3.3	
					N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A	
	BU A				N/A	Flare Slope LT (%)	7.6	Yes	Flare Slope RT (%)	5.9	
AND AND					N/A	Flare Traversable LT?	Yes	N/A	Flare Traversable RT?	Yes	
A CONTRACTOR					No	Landing Length (in)	N/A	Yes	DWS Provided?	Yes	
		Surveyor Notes:			No	Landing Width (in)	N/A	Yes	DWS Contrast?	Yes	
the second se	A.	N/A			No	Landing Slope (%)	N/A	Yes	DWS Length (in)	24.0	
A A A A A A A A A A A A A A A A A A A					No	Landing X Slope (%)	N/A	Yes	DWS Full Width?	Yes	
All and a second	ALL C				N/A	Landing Curb? (Y/N)	No	No	DWS Offset (in)	4.5	
Test of		<b>&gt;</b>			N/A	Shared Landing?	No				
11/1000		PROW/ADA:			Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	4.6	
	San V	R304.5.3, R304.2.1, R304	rp.	No	Gutter Lip Ht (in)	1.0	Yes	Gutter X Slope (%)	1.4		
	R304.3.2-Para, R305.2, F	• *	N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A			
					X Walk 1 Direction	To SE		X Walk 2 Direction	N/A		
	116 29				N/A	X Walk 1 Width (in)	115.0	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	S TRYON ST					X Walk 1 Slope (%)	3.9		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	Signal					X Walk 1 X Slope (%)	0.2		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A				Yes	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	Yes	
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
					Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No	
		Total Cost:	\$	2050.00		Obstruction Type			Storm Grate/Utility Type		
							N/A			N/A	

Yes Surface Condition? (G/P) Good

