

Access Compliance Report Public Rights-of-Way (Curb Ramps)



| Intersection ID: 53413 | Main Str | Main Street: GOLF_LINKS_DR | | | Cross Street: WAVERLY_WALK_AV | | | | E |
|---|-----------------|----------------------------|---------------|---|--|------------|-----|-----------------------------|------------|
| ADA ID: 7C1E7D239735 | Ramp Ty | Ramp Type: Perp | | | Initial Pass/Fail: Fail Overall Compliance: No | | | o Severity Score: | 21.25 |
| Codes/Mitigation Info/Possible Solution | | | | Field Measurements/Component Compliance | | | | | |
| | | Possible Solutions: | | | | | | Compliance Description Data | |
| | | Remove & Replace | Entiro Ramo | N/A | Ramp Length (in) | 63.0 | No | Ramp Slope (%) | 9.0 |
| | 11138 | | Entre Ramp. | No | Ramp Width (in) | 47.5 | Yes | Ramp XSlope (%) | 0.5 |
| | TABE / | | | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| | 1 1285 17 | 7 | | N/A | Flare Slope LT (%) | N/A | | Flare Slope RT (%) | N/A |
| John | Mar Aller | | | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| | | | | N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| 537 | and a second | Surveyor Notes: | | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| | 1 top to 10 | N/A | | N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| | No star | N/A | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| | 1. 2. 2 | | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| the second second | E Contraction | | | N/A | Shared Landing? | N/A | | 2 | |
| | A Day | PROW/ADA: | | N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| I TETTION | AL AV | Not Found, R304.5 | 1 0204 2 2 | N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A |
| | 777. | | 0.1, K304.2.2 | N/A | Painted X Walk1? | Yes | N/A | Painted X Walk2? | N/A |
| | | 1 | | | X Walk 1 Direction | To SW | | X Walk 2 Direction | N/A |
| A T INHITD | A A | | | N/A | X Walk 1 Width (in) | 104.0 | N/A | X Walk 2 Width (in) | N/A |
| Street 1 Name | WAVERLY WALK AV | - | | 170 | X Walk 1 Slope (%) | 2.0 | | X Walk 2 Slope (%) | N/A |
| Stop Condition-Street 2 | StopSign | | | | X Walk 1 X Slope (%) | 2.0 1.5 | | X Walk 2 X Slope (%) | N/A N/A |
| Street 2 Name | N/A | | | N/A | Ramp inside XWalk1? | Yes | N/A | Ramp inside XWalk2? | N/A |
| Stop Condition-Street 1 | N/A | | | 10/4 | Road Slope (%) | N/A | N/A | Clear Space? | N/A |
| Stop Condition-Street 1 | N/A | | | | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A N/A |
| | | | | N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A N/A |
| | | Total Cost: | ¢ 4 | 850.00 | Obstruction Type | IN/A | | Storm Grate/Utility Type | IN/A |
| | | 101a1 0081. | φ 10 | 000.00 | Obstruction Type | NI/A | | Storm Grate/Otimity Type | N/A |
| | | | | | | N/A | | | N/A |

Yes Surface Condition? (G/P)

Good

