

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Surface Condition? (G/P)

Curb Slope (%)

Good

N/A

Yes

N/A

Intersection ID: 9316	rsection ID: 9316 Main Street: KARENSTONE_DR				THE_PLAZA	Location:	SW		
ADA ID: 7D19FC3842B8	Ramp Type: BlendTrans1			itial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	1.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	La construction of the second	Possible Solutions:		Compliance Description			Data Compliance Description		
		Remove & Replace Curb Ramp V	Vith	N/A	Ramp Length (in)	62.5	Yes	BlendTrans Slope (%)	2.9
		Two New Directional Ramps or Equivalent.		Yes	Ramp Width (in)	72.0	No	BlendTrans XSlope (%)	2.9
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
A. A. A. A. A.				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
Real Providence				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
The Thirt				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
W.S.		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
& K		NOCURB		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
6	1 Alexandre			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
	· P	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	A B	R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Alla Sala Andreas		Recencie		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	Q			X Walk 1 Direction	To NE		X Walk 2 Direction	N/A	
all an indian in the	1 . B. B.	5			X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	Name KARENSTONE DR				X Walk 1 Slope (%)	0.7		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	StopSign				X Walk 1 X Slope (%)	1.3		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A				Road Slope (%)	1.3		Clear Space?	N/A
					Road X Slope (%)	0.7	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 32	200.00	•	Obstruction Type			Storm Grate/Utility Type	
		•••••••••••••••••••••••••••••••••••••••				N/A			N/A
						10/3			



