

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: 28651 Main Street: MARVIN\_RD Cross Street: PRINCETON\_COMMONS\_DR Location: NE ADA ID: 7D5E4C690800 Ramp Type: Perp Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 42.5

**Codes/Mitigation Info/Possible Solution** 



**MARVIN RD** Street 1 Name Stop Condition-Street 2 None Street 2 Name N/A Stop Condition-Street 1 N/A Possible Solutions: Remove & Replace Entire Ramp. Surveyor Notes: N/A PROW/ADA: R304.5.1, R304.5.3

Total Cost: 1850.00

Field Measurements/Component Compliance						
Compliance Description		Data	Compliance		Description	Data
N/A	Ramp Length (in)	137.0	Yes	Ram	Slope (%)	7.7
No	Ramp Width (in)	33.0	No	Ramp XSlope (%)		9.6
N/A	Flare Type LT	N/A	N/A	/A Flare Type RT		N/A
N/A	Flare Slope LT (%)	N/A	N/A	A Flare Slope RT (%)		N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?		N/A
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?		N/A
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutte	er Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	er X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?	N/A
	X Walk 1 Direction	To SW		X Wa	lk 2 Direction	N/A
N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	ılk 2 Width (in)	N/A
	X Walk 1 Slope (%)	5.8		X Wa	lk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	4.8		X Wa	lk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ram	o inside XWalk2?	N/A
	Road Slope (%)	N/A	N/A	Clear	Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storn	n Grate/Utility Hazard?	N/A
	Obstruction Type			Storn	n Grate/Utility Type	
		N/A				N/A
			Yes	Surfa	ce Condition? (G/P)	Good
	· 发生。					





