

Access Compliance Report Public Rights-of-Way (Curb Ramps)



| Intersection ID: 14281 | Main Str | Main Street: E_KINGSTON_AV | | Cross Street: LYNDHURST_AV | | | Location: S | | S | | |
|---|---------------------|------------------------------|--|----------------------------|---|-----------------------------|-------------|-----------------------------|------|--|--|
| ADA ID: 7F7EE50C5C80 | Ramp Ty | Initial Pa | Initial Pass/Fail: Fail Overall Complian | | | nce: No Severity Score: 1.2 | | 1.25 | | | |
| Codes/Mitigation Info/Possible Solution | | | | | Field Measurements/Component Compliance | | | | | | |
| | Possible Solutions: | Compliance Description D | | | Data | Data Compliance Description | | | | | |
| | C. S / S.C. | Remove & Replace Entire Ramp | - | N/A | Ramp Length (in) | 84.0 | N/A | Grade Break? | N/A | | |
| The state of the state | | | | Yes | Ramp Width (in) | 65.0 | N/A | Grade Break Slope (%) | 0.0 | | |
| A second | 1 7 6 | | | Yes | Ramp Slope (%) | 3.1 | N/A | Grade Break XSlope (%) | 0.0 | | |
| | Steller | | | No | Ramp XSlope (%) | 2.1 | | | | | |
| the the | A- B | | | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A | | |
| | 1 | | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | 0.0 | | |
| | WALL AN | Surveyor Notes: | | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A | | |
| the second | | N/A | | N/A | Landing Length (in) | 0.0 | N/A | DWS Provided? | N/A | | |
| 53 | COROL OF | | | N/A | Landing Width (in) | 0.0 | N/A | DWS Contrast? | N/A | | |
| A State | | | | N/A | Landing Slope (%) | 0.0 | N/A | DWS Length (in) | N/A | | |
| | 1 2 1 2 2 | | | N/A | Landing X Slope (%) | 0.0 | N/A | DWS Full Width? | N/A | | |
| | the the | PROW/ADA: | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset LT (in) | N/A | | |
| | LEN CA | R304.5.3 | | N/A | Shared Landing? | N/A | N/A | DWS Offset RT (in) | N/A | | |
| | 1 1 | | | N/A | Gutter Ponding? | 0.0 | N/A | Gutter Slope (%) | N/A | | |
| Nation Labor 1 | | | | N/A | Gutter Lip Ht (in) | 0.0 | N/A | Gutter X Slope (%) | N/A | | |
| | V / A sun | | | N/A | Painted X Walk1? | No | | Road Slope (%) | 2.1 | | |
| Street 1 Name | LYNDHURST AV | | | | X Walk 1 Direction | To NW | | Road X Slope (%) | 0.1 | | |
| Stop Condition-Street 1 | StopSign | | | | X Walk 1 Width (in) | N/A | | Clear Space? | N/A | | |
| Street 2 Name | N/A | | | | X Walk 1 Slope (%) | 2.1 | N/A | Clear Space to XWalk (in) | N/A | | |
| Stop Condition-Street 2 | N/A | | | | X Walk 1 X Slope (%) | 0.1 | N/A | Storm Grate/Utility Hazard? | N/A | | |
| | | | | N/A | Ramp inside XWalk1? | N/A | | Storm Grate/Utility Type | | | |
| | | | | N/A | Any Obstructions? | N/A | | | N/A | | |
| | | Total Cost: \$ | 1600.00 | | Obstruction Type | | Yes | Surface Condition? (G/P) | Good | | |
| | | | | | | N/A | N/A | Curb Slope (%) | 2.6 | | |

