

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A

Curb Slope (%)

9.5

t: MIRAMAR_DR	Cross Str	eet:	PURSER_DR	Location:	NE			
: Para	Initial Pas	ss/Fa	il: Fail Overall (	Severity Score:	12.5			
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance						
ossible Solutions:	<u>c</u>	Compliance Description Data			Compliance Description		Data	
Remove & Replace Entire Ram	). N	I/A	Ramp Length LT (in)	59.0	N/A	Ramp Length RT (in)	51.5	
		'es	Ramp Width LT (in)	59.0	Yes	Ramp Width RT (in)	60.0	
	N	lo	Ramp Slope LT (%)	9.0	Yes	Ramp Slope RT (%)	3.0	
	Y	'es	Ramp XSlope LT (%)	0.2	Yes	Ramp XSlope RT (%)	0.9	
	N	I/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	N	I/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
urveyor Notes:	N	I/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
RT RP < 5%	N	I/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	N	I/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
	N	I/A	Shared Landing?	N/A				
	N	I/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
ROW/ADA:	N	/ <b>A</b>	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
R304.3.2	N	I/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
			X Walk 1 Direction	To NW		X Walk 2 Direction	N/A	
	N	I/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
			X Walk 1 Slope (%)	2.1		X Walk 2 Slope (%)	N/A	
			X Walk 1 X Slope (%)	0.4		X Walk 2 X Slope (%)	N/A	
	N	I/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
			Road Slope (%)	N/A	N/A	Clear Space?	N/A	
			Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
	N	I/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
			Obstruction Type			Storm Grate/Utility Type		
otal Cost: \$	1600.00		• •	N/A			N/A	
					Yes	Surface Condition? (G/P)	Good	
	Para ssible Solution ssible Solutions: temove & Replace Entire Ramp rveyor Notes: T RP < 5% OW/ADA: 304.3.2	Para       Initial Pase         ssible Solutions:       C         ssible Solutions:       C         cemove & Replace Entire Ramp.       N         veyor Notes:       N         TRP < 5%	Para       Initial Pass/Fa         ssible Solutions:       Compl         ssible Solutions:       Compl         semove & Replace Entire Ramp.       N/A         Yes       No         Yes       No         Yes       N/A         Yeyor Notes:       N/A         TRP < 5%	Para       Initial Pass/Fail: Fail       Overall (         ssible Solution       Field Measure         ssible Solutions:       Compliance Description         Remove & Replace Entire Ramp.       N/A       Ramp Length LT (in)         Yes       Ramp Width LT (in)         Yes       Ramp Width LT (in)         Yes       Ramp XSlope LT (%)         Yes       Ramp XSlope LT (%)         Yes       Ramp XSlope LT (%)         N/A       Landing Length (in)         N/A       Landing Slope (%)         N/A       Landing Slope (%)         N/A       Landing Curb? (Y/N)         N/A       Slope (%)         N/A       Gutter Ponding?         OW/ADA:       N/A       Gutter Lip Ht (in)         :304.3.2       N/A       Painted X Walk1?         X Walk 1 Direction       N/A       XWalk 1 Width (in)         X Walk 1 Slope (%)       X/A       Ramp inside XWalk1?         N/A       Ramp inside XWalk1?       Road Slope (%)         N/A       Any Obstructions?       Obstruction Type	Para       Initial Pass/Fail: Fail       Overall Compliant         ssible Solutions:       Field Measurements/C         ssible Solutions:       Compliance Description       Data         teemove & Replace Entire Ramp.       N/A       Ramp Length LT (in)       59.0         Yes       Ramp Width LT (in)       59.0         No       Ramp Slope LT (%)       9.0         Yes       Ramp XSlope LT (%)       0.2         N/A       Landing Length (in)       N/A         veyor Notes:       N/A       Landing Slope (%)       N/A         TRP < 5%	Para       Initial Pass/Fail: Fail       Overall Compliance: Notestation         ssible Solution       Field Measurements/Components         permove & Replace Entire Ramp.       N/A       Ramp Length LT (in)       59.0       N/A         Yes       Ramp Width LT (in)       59.0       Yes         No       Ramp Slope LT (%)       9.0       Yes         Yes       Ramp Slope LT (%)       9.0       Yes         N/A       Landing Length (in)       N/A       N/A         veyor Notes:       N/A       Landing Slope (%)       N/A         TRP < 5%	Para       Initial Pass/Fail:       Fail       Overall Compliance:       No       Severity Score:         ssible Solutions:       Compliance       Description       Data       Compliance       Description         serve & Replace Entire Ramp.       N/A       Ramp Length LT (in)       \$9.0       Yes       Ramp Slope LT (%)       9.0       Yes       Ramp Slope RT (%)         Yes       Ramp XSlope LT (%)       9.0       Yes       Ramp XSlope RT (%)       Yes       Ramp XSlope RT (%)         Yes       Ramp XSlope LT (%)       0.2       Yes       Ramp XSlope RT (%)       WA         Yes       Ramp XSlope LT (%)       N/A       DWS Provided?         N/A       Landing Udth (in)       N/A       N/A       DWS Contrast?         veyor Notes:       N/A       Landing Slope (%)       N/A       N/A       DWS Contrast?         Veyor Notes:       N/A       Landing Curb? (Y/N)       N/A       N/A       DWS Offset (in)         TT RP < 5%	

