

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

1.4

8.2

N/A

N/A

N/A

N/A

N/A

N/A

N/A N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

8.2

Good

Main Street: BELL'S MILL DR Cross Street: N/A Location: Ε Intersection ID: 1000791 **ADA ID: 7FECD416629C** Initial Pass/Fail: Fail **Overall Compliance: No** 25 Ramp Type: BlendTrans2 **Severity Score:**

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Yes

N/A

N/A

N/A

N/A

N/A

N/A

Yes

No

Compliance Description

Flare Type RT

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

Flare Traversable RT?

Surface Condition? (G/P)

Curb Slope (%)

BlendTrans Slope (%)

BlendTrans XSlope (%)

Data

56.0

55.0 No

N/A

N/A

N/A

N/A

N/A

N/A



Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

treet 1 Name	CHRISTENBURY PARK
op Condition-Street 1	None
reet 2 Name	N/A
op Condition-Street 2	N/A

		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?
		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)
		N/A	Shared Landing?	N/A		
PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)
Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)
· ·		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?
			X Walk 1 Direction	To NW		X Walk 2 Direction
			X Walk 1 Width (in)	N/A		X Walk 2 Width (in)
			X Walk 1 Slope (%)	2.8		X Walk 2 Slope (%)
			X Walk 1 X Slope (%)	2.7		X Walk 2 X Slope (%)
		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?
			Road Slope (%)	2.7		Clear Space?
			Road X Slope (%)	2.8	N/A	Clear Space to XWalk (in)
		N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?
Total Cost:	\$ 3200.00		Obstruction Type			Storm Grate/Utility Type
				N/A		

Compliance Description

N/A

Yes

N/A

N/A

N/A

N/A

N/A

N/A

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Flare Traversable LT?

Flare Type LT





