

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10034319Main Street: PERIMETER\_PYCross Street: N/ALocation: NWADA ID: 80698AA21D32Ramp Type: PerpDiagInitial Pass/Fail: Fail Overall Compliance: No Severity Score: 10

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

PERIMETER PY
None
ENTRANCE
StopSign

Possible Solutions:

Remove & Replace Curb Ramp With
Two New Directional Ramps or
Equivalent.

Surveyor Notes:
N/A

PROW/ADA:
Not Found, R304.5.1, R304.5.3

Sign

| Compliance Description |                       | Data | Compliance Description |                             | Data |
|------------------------|-----------------------|------|------------------------|-----------------------------|------|
| N/A                    | Ramp Length (in)      | 67.0 | Yes                    | Ramp Slope (%)              | 8.2  |
| No                     | Ramp Width (in)       | 47.0 | No                     | Ramp XSlope (%)             | 2.9  |
| N/A                    | Flare Type LT         | N/A  | N/A                    | Flare Type RT               | N/A  |
| N/A                    | Flare Slope LT (%)    | N/A  | N/A                    | Flare Slope RT (%)          | N/A  |
| N/A                    | Flare Traversable LT? | N/A  | N/A                    | Flare Traversable RT?       | N/A  |
| N/A                    | Landing Length (in)   | N/A  | N/A                    | DWS Provided?               | N/A  |
| N/A                    | Landing Width (in)    | N/A  | N/A                    | DWS Contrast?               | N/A  |
| N/A                    | Landing Slope (%)     | N/A  | N/A                    | DWS Length (in)             | N/A  |
| N/A                    | Landing X Slope (%)   | N/A  | N/A                    | DWS Full Width?             | N/A  |
| N/A                    | Landing Curb? (Y/N)   | N/A  | N/A                    | DWS Offset (in)             | N/A  |
| N/A                    | Shared Landing?       | N/A  |                        |                             |      |
| N/A                    | Gutter Ponding?       | N/A  | N/A                    | Gutter Slope (%)            | N/A  |
| N/A                    | Gutter Lip Ht (in)    | N/A  | N/A                    | Gutter X Slope (%)          | N/A  |
| N/A                    | Painted X Walk1?      | Yes  | N/A                    | Painted X Walk2?            | Yes  |
|                        | X Walk 1 Direction    | To S |                        | X Walk 2 Direction          | To E |
| N/A                    | X Walk 1 Width (in)   | 72.0 | N/A                    | X Walk 2 Width (in)         | 72.0 |
|                        | X Walk 1 Slope (%)    | 1.8  |                        | X Walk 2 Slope (%)          | 0.4  |
|                        | X Walk 1 X Slope (%)  | 2.7  |                        | X Walk 2 X Slope (%)        | 0.8  |
| N/A                    | Ramp inside XWalk1?   | Yes  | N/A                    | Ramp inside XWalk2?         | Yes  |
|                        | Road Slope (%)        | 4.0  | N/A                    | Clear Space?                | N/A  |
|                        | Road X Slope (%)      | 1.2  | N/A                    | Clear Space to XWalk (in)   | N/A  |
| N/A                    | Any Obstructions?     | N/A  | N/A                    | Storm Grate/Utility Hazard? | N/A  |
|                        | Obstruction Type      |      |                        | Storm Grate/Utility Type    |      |
|                        |                       | N/A  |                        |                             | N/A  |
|                        |                       |      |                        |                             |      |

Yes

Surface Condition? (G/P)

Good





Total Cost:



3200.00