

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 23437 Main Street: TRYON_ST Cross Street: MOSS_LN Location: Ε Severity Score: **Overall Compliance: No** ADA ID: 80EB002D919D Ramp Type: MedianPerp Initial Pass/Fail: Pass 5.25

Codes/Mitigation Info/Possible Solution



Street 1 Name	S TRYON ST
Stop Condition-Street 2	Signal
Street 2 Name	N/A
Ston Condition-Street 1	N/A

Possible Solution
Possible Solutions:
Remove & Replace Entire Ramp. Remove & Replace Gutter.
Surveyor Notes:
PROW/ADA: Not Found, R304.5.3, R304.2.1,
R302.7, R304.5.4

Tatal Cast	•	0400.00
Total Cost:	\$	2400.00

Field Measurements/Component Compliance								
Comp	liance Description	Data	Comp	liance Description	Data			
N/A	Ramp Length (in)	64.0	Yes	Ramp Slope (%)	5.4			
Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	2.2			
N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A			
N/A	Flare Slope LT (%)	4.3	Yes	Flare Slope RT (%)	3.7			
N/A	Flare Traversable LT?	Yes	N/A	Flare Traversable RT?	Yes			
No	Landing Length (in)	36.0	Yes	DWS Provided?	Yes			
Yes	Landing Width (in)	48.0	Yes	DWS Contrast?	Yes			
Yes	Landing Slope (%)	0.6	Yes	DWS Length (in)	25.5			
Yes	Landing X Slope (%)	0.9	Yes	DWS Full Width?	Yes			
N/A	Landing Curb? (Y/N)	N/A	Yes	DWS Offset (in)	0.0			
N/A	Shared Landing?	Yes						
No	Gutter Ponding?	Yes	No	Gutter Slope (%)	6.9			
Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.2			
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A			
	X Walk 1 Direction	To N		X Walk 2 Direction	N/A			
N/A	X Walk 1 Width (in)	119.0	N/A	X Walk 2 Width (in)	N/A			
	X Walk 1 Slope (%)	2.4		X Walk 2 Slope (%)	N/A			
	X Walk 1 X Slope (%)	1.0		X Walk 2 X Slope (%)	N/A			
Yes	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A			
	Road Slope (%)	N/A	N/A	Clear Space?	Yes			
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A			
Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No			
	Obstruction Type			Storm Grate/Utility Type				
		N/A			N/A			
			Yes	Surface Condition? (G/P)	Good			
1								





