

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 48558Main Street: ARDREY_WOODS_DRCross Street: N/ALocation: WADA ID: 829C07D7976BRamp Type: PerpDiagInitial Pass/Fail: FailOverall Compliance: NoSeverity Score: 30

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

ARDREY WOODS DR StopSign ARDREY WOODS DR None Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.5.3

Total Cost: \$ 3200.00

Field Measurements/Component Compliance							
Compl		liance Description	Data	Comp	liance [Description	Data
	N/A	Ramp Length (in)	72.0	Yes	Ramp S	Slope (%)	5.3
	No	Ramp Width (in)	33.0	No	Ramp >	XSlope (%)	6.3
	N/A	Flare Type LT	N/A	N/A	Flare T	ype RT	N/A
	N/A	Flare Slope LT (%)	N/A	N/A	Flare S	Slope RT (%)	N/A
	N/A	Flare Traversable LT?	N/A	N/A	Flare T	raversable RT?	N/A
	N/A	Landing Length (in)	N/A	N/A	DWS P	Provided?	N/A
	N/A	Landing Width (in)	N/A	N/A	DWS C	Contrast?	N/A
	N/A	Landing Slope (%)	N/A	N/A	DWS L	ength (in)	N/A
	N/A	Landing X Slope (%)	N/A	N/A	DWS F	full Width?	N/A
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS C	Offset (in)	N/A
	N/A	Shared Landing?	N/A				
	N/A	Gutter Ponding?	N/A	N/A	Gutter	Slope (%)	N/A
	N/A	Gutter Lip Ht (in)	1.0	N/A	Gutter	X Slope (%)	N/A
	N/A	Painted X Walk1?	No	N/A	Painted	d X Walk2?	No
		X Walk 1 Direction	To SE		X Walk	2 Direction	To NE
	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk	2 Width (in)	N/A
		X Walk 1 Slope (%)	2.2		X Walk	2 Slope (%)	3.6
		X Walk 1 X Slope (%)	3.6		X Walk	2 X Slope (%)	0.5
	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp i	inside XWalk2?	N/A
		Road Slope (%)	5.5	N/A	Clear S	Space?	N/A
		Road X Slope (%)	3.2	N/A	Clear S	Space to XWalk (in)	N/A
	N/A	Any Obstructions?	N/A	N/A	Storm (Grate/Utility Hazard?	N/A
		Obstruction Type			Storm (Grate/Utility Type	
			N/A				N/A
				Yes	Surface	e Condition? (G/P)	Good





