## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



· · · · · · · · · · · · · · · · · · ·									
Intersection ID: 43742 Main Str		eet: RED_CLAY_LN	Cross Street: VANHOY_LN				Location:	SE	
ADA ID: 83937F64E	DA ID: 83937F64E5E6 Ramp Type: PerpDiag		Initial Pass/Fail: Fail Overall Compliance:				ice: N	o Severity Score:	58.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description		Data Compliance Description		Data	
Territoria and the second second		Remove & Replace Curb Ramp	Vith	N/A	Ramp Length (in)	48.0	No	Ramp Slope (%)	16.7
AND ALL		Two New Directional Ramps or		No	Ramp Width (in)	40.0	No	Ramp XSlope (%)	10.4
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
VANHOY_LIN SU		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
<u>ь.</u>		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		Te		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
and the second s		PROW/ADA:		N/A	Shared Landing?	N/A			
Territory and				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1, R304.2.2,		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
		R304.5.3		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To N		X Walk 2 Direction	To W
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	VANHOY LN				X Walk 1 Slope (%)	1.1		X Walk 2 Slope (%)	5.3
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	6.0		X Walk 2 X Slope (%)	5.2
Street 2 Name	RED CLAY LN			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	7.7	N/A	Clear Space?	N/A
					Road X Slope (%)	2.7	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

**Yes** Surface Condition? (G/P)

Good

