

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 12401 Ma	: 12401 Main Street: MIDWOOD_PL		Cross Street: TIPPAH_AV			NE	
ADA ID: 866C1A76CAFD Ramp Type: Perp		Initial Pass	Initial Pass/Fail: Fail Overall Compliance: No		: No Severity Score:	13.75	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance				
Possible Solutions:		Cor	Compliance Description Data Compliance			Data	
	Remove & Replace Entire Ram). N/A	Ramp Length (in)	65.0 No	o Ramp Slope (%)	9.3	
Manager and Manager & The		Yes	Ramp Width (in)	48.0 No	• Ramp XSlope (%)	4.5	
the state of the second st		N/A	Flare Type LT	N/A N/	/A Flare Type RT	N/A	
		N/A		N/A N/		N/A	
		N/A	Flare Traversable LT?	N/A N/	A Flare Traversable RT?	N/A	
		N/A	Landing Length (in)	N/A N/	A DWS Provided?	N/A	
	Surveyor Notes:	N/A	Landing Width (in)	N/A N/	A DWS Contrast?	N/A	
	N/A	N/A	Landing Slope (%)	N/A N/	/A DWS Length (in)	N/A	
	SPECE L	N/A	Landing X Slope (%)	N/A N/	A DWS Full Width?	N/A	
A State of the second s	50 B	N/A	Landing Curb? (Y/N)	N/A N/	/A DWS Offset (in)	N/A	
Strange Strange in	Constant of the second s	N/A		N/A			
	PROW/ADA:	N/A	Gutter Ponding?	N/A N/	A Gutter Slope (%)	N/A	
	Not Found, R304.2.2, R304.5.3	N/A	Gutter Lip Ht (in)	1.0 N/		N/A	
		N/A	Painted X Walk1?	No N/	/A Painted X Walk2?	N/A	
			X Walk 1 Direction	то W	X Walk 2 Direction	N/A	
The Set of		N/A	X Walk 1 Width (in)	N/A N/	/A X Walk 2 Width (in)	N/A	
Street 1 Name TIPPA	H AV		X Walk 1 Slope (%)	1.6	X Walk 2 Slope (%)	N/A	
	lone		X Walk 1 X Slope (%)	3.6	X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A	N/A	,	N/A N/		N/A	
Stop Condition-Street 1	N/A		Road Slope (%)	N/A N/	/A Clear Space?	N/A	
			Road X Slope (%)	N/A N/	/A Clear Space to XWalk (in)	N/A	
		N/A		N/A N/		N/A	
	Total Cost: \$	1850.00	Obstruction Type		Storm Grate/Utility Type		
				N/A		N/A	