

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: PEPPERPIKE_WY			Cross	Cross Street: MORGAN_LEE_AV				Location:	W
Ramp Type: Perp			Initial	Initial Pass/Fail: Fail Overall Compliance:				o Severity Score:	10
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
P	Possible Solutions:			Compliance Description Data			Compliance Description		Data
10	Remove & Replace Entire	Ram	<b>D</b> .	N/A	Ramp Length (in)	49.5	Yes	Ramp Slope (%)	5.8
and the second				No	Ramp Width (in)	47.0	Yes	Ramp XSlope (%)	2.1
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%	6) <b>N/A</b>	N/A	Flare Slope RT (%)	N/A
1 9				N/A	Flare Traversable	LT? <b>N/A</b>	N/A	Flare Traversable RT?	N/A
1 hr				N/A	Landing Length (ir	n) <b>N/A</b>	N/A	DWS Provided?	N/A
S	Surveyor Notes:			N/A	Landing Width (in)	) <b>N/A</b>	N/A	DWS Contrast?	N/A
	N/A			N/A	Landing Slope (%	) <b>N/A</b>	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (	(%) <b>N/A</b>	N/A	DWS Full Width?	N/A
**				N/A	Landing Curb? (Y	/N) <b>N/A</b>	N/A	DWS Offset (in)	N/A
- 3021				N/A	Shared Landing?	N/A			
P	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
190	Not Found, R304.5.1			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
12				N/A	Painted X Walk1?	, No	N/A	Painted X Walk2?	N/A
E					X Walk 1 Directior	n <b>To E</b>		X Walk 2 Direction	N/A
				N/A	X Walk 1 Width (ir	n) <b>N/A</b>	N/A	X Walk 2 Width (in)	N/A
PIKE WY					X Walk 1 Slope (%	%) 3.7		X Walk 2 Slope (%)	N/A
None					X Walk 1 X Slope	(%) 3.1		X Walk 2 X Slope (%)	N/A
N/A				N/A	Ramp inside XWa	alk1? <b>N/A</b>	N/A	Ramp inside XWalk2?	N/A
N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	) <b>N/A</b>	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions	? <b>N/A</b>	N/A	Storm Grate/Utility Hazard?	N/A
То	otal Cost:	\$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A
t	Ramp Type ion Info/P	Ramp Type: Perp sion Info/Possible Solution Possible Solutions: Remove & Replace Entire Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1	Ramp Type: Perp sion Info/Possible Solution Possible Solutions: Remove & Replace Entire Ram Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1	Ramp Type: Perp   Initial     ion Info/Possible Solutions:     Possible Solutions:     Remove & Replace Entire Ramp.     Surveyor Notes:     N/A     PROW/ADA:     None     N/A	Ramp Type: Perp   Initial Pass/Fa     tion Info/Possible Solutions:   Comp     Remove & Replace Entire Ramp.   N/A     N/A   N/A	Ramp Type: Perp   Initial Pass/Fail: Fail     tion Info/Possible Solution   Field M     Possible Solutions:   Compliance Description     Remove & Replace Entire Ramp.   N/A     N/A   Ramp Width (in)     N/A   Flare Slope LT (%     N/A   Landing Length (in)     N/A   Landing Slope (%     N/A   N/A     N/A   Landing Slope (%)     N/A   Kuster Ponding?     N/A   Gutter Lip Ht (in)     N/A   N/A     N/A   N/A     N/A   Kuster Lip Ht (in)     N/	Ramp Type:   Perp   Initial Pass/Fail:   Fail   Overall Compliant     tion Info/Possible Solutions:   Field Measurements/C   Edd Measurements/C     Possible Solutions::   Remove & Replace Entire Ramp.   N/A   Ramp Length (in)   49.5     No   Ramp Uength (in)   49.5   No   Ramp Length (in)   49.5     No   Ramp Length (in)   49.5   No   Ramp Length (in)   49.5     No   Ramp Uength (in)   49.5   No   Ramp Length (in)   49.5     No   Ramp Uength (in)   49.5   No   Ramp Uength (in)   49.5     N/A   Flare Stope LT (%)   N/A   N/A   Flare Stope LT (%)   N/A     N/A   Flare Stope LT (%)   N/A   N/A   Landing Length (in)   N/A     N/A   Landing Stope (%)   N/A   N/A   Landing Curb? (Y/N)   N/A     N/A   N/A   Landing Curb? (Y/N)   N/A   N/A   N/A   Kalth 1 Direction   To E     N/A   N/A   Gutter Ponding?   N/A   N/A   XWalk 1 Stope (%)   3.7     N/A   N/A   N/A	Ramp Type:   Perp   Initial Pass/Fail:   Fail   Overall Compliance:   N     ion Info/Possible Solution   Field Measurements/Compo   Data   Compliance   Description   Data   Compliance   Data   Data	Ramp Type: Perp Initial Pass/Fail: Sveral Compliance: No Severity Score:   ton Info/Possible Solution: Field Measurements/Component Compliance Compliance Description Data Compliance Description   Possible Solutions: Remove & Replace Entire Ramp. N/A Ramp Length (in) 49.5 Yes Ramp Slope (%)   N/A Flare Type LT N/A Flare Stope LT (%) N/A Flare Stope RT (%)   N/A Flare Traversable LT? N/A Flare Traversable RT? N/A Flare Stope RT (%)   N/A Flare Traversable LT? N/A N/A Flare Stope RT (%) N/A Flare Traversable RT?   N/A Flare Traversable LT? N/A Landing Urdth (in) N/A N/A DWS Forvided?   N/A Landing Stope (%) N/A N/A DWS Full Width? N/A DWS Length (in)   N/A Landing Stope (%) N/A Landing Stope (%) N/A N/A DWS Full Width?   N/A Landing Stope (%) N/A N/A DWS Full Width? N/A   N/A Gutter Ponding? N/A M/A DWS Full Width?   N/A Gutter Conding? N/A N/A Gutter Stope (%)   N/A

Yes Surface Condition? (G/P)

Good

