

# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

|   |                           |   |                        |
|---|---------------------------|---|------------------------|
| Intersection ID: 4764                   | Main Street: ELDERBANK_DR | Cross Street: TRINITY_RD                | Location: NW           |
| ADA ID: 885931CF6459                    | Ramp Type: BlendTrans2    | Initial Pass/Fail: Fail                 | Overall Compliance: No |
| Severity Score: 17.5                    |                           |   |                        |
| Codes/Mitigation Info/Possible Solution |                           | Field Measurements/Component Compliance |                        |

|   |  |            |            |                       |             |     |                             |            |             |      |
|---|--|------------|------------|-----------------------|-------------|-----|-----------------------------|------------|-------------|------|
|                         | Possible Solutions:  |            | Compliance |                       | Description |     | Data                        | Compliance | Description | Data |
|   | Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. |            | N/A        | Ramp Length (in)      | 70.0        | Yes | BlendTrans Slope (%)        | 3.4        |             |      |
| <p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>Not Found, R304.5.1</p>                           |  |            | No         | Ramp Width (in)       | 33.0        | Yes | BlendTrans XSlope (%)       | 0.5        |             |      |
|   |  |            | N/A        | Flare Type LT         | N/A         | N/A | Flare Type RT               | N/A        |             |      |
| <p>Street 1 Name</p> <p>Stop Condition-Street 1</p> <p>Street 2 Name</p> <p>Stop Condition-Street 2</p> |  |            | N/A        | Flare Slope LT (%)    | N/A         | N/A | Flare Slope RT (%)          | N/A        |             |      |
|   |  |            | N/A        | Flare Traversable LT? | N/A         | N/A | Flare Traversable RT?       | N/A        |             |      |
|   |  |            | N/A        | Landing Length (in)   | N/A         | N/A | DWS Provided?               | N/A        |             |      |
|   |  |            | N/A        | Landing Width (in)    | N/A         | N/A | DWS Contrast?               | N/A        |             |      |
|   |  |            | N/A        | Landing Slope (%)     | N/A         | N/A | DWS Length (in)             | N/A        |             |      |
|   |  |            | N/A        | Landing X Slope (%)   | N/A         | N/A | DWS Full Width?             | N/A        |             |      |
|   |  |            | N/A        | Landing Curb? (Y/N)   | N/A         | N/A | DWS Offset (in)             | N/A        |             |      |
|   |  |            | N/A        | Shared Landing?       | N/A         |     |                             |            |             |      |
|   |  |            | N/A        | Gutter Ponding?       | N/A         | N/A | Gutter Slope (%)            | N/A        |             |      |
|   |  |            | N/A        | Gutter Lip Ht (in)    | N/A         | N/A | Gutter X Slope (%)          | N/A        |             |      |
|   |  |            | N/A        | Painted X Walk1?      | No          | N/A | Painted X Walk2?            | N/A        |             |      |
|   |  |            |            | X Walk 1 Direction    | To S        |     | X Walk 2 Direction          | N/A        |             |      |
|   |  |            |            | X Walk 1 Width (in)   | N/A         |     | X Walk 2 Width (in)         | N/A        |             |      |
|   |  |            |            | X Walk 1 Slope (%)    | 0.7         |     | X Walk 2 Slope (%)          | N/A        |             |      |
|   |  |            |            | X Walk 1 X Slope (%)  | 0.1         |     | X Walk 2 X Slope (%)        | N/A        |             |      |
|   |  |            | N/A        | Ramp inside XWalk1?   | N/A         | N/A | Ramp inside XWalk2?         | N/A        |             |      |
|   |  |            |            | Road Slope (%)        | 0.1         |     | Clear Space?                | N/A        |             |      |
|   |  |            |            | Road X Slope (%)      | 0.7         | N/A | Clear Space to XWalk (in)   | N/A        |             |      |
|   |  |            | N/A        | Any Obstructions?     | N/A         | N/A | Storm Grate/Utility Hazard? | N/A        |             |      |
|   |  |            |            | Obstruction Type      |             |     | Storm Grate/Utility Type    |            |             |      |
| Total Cost:   |  | \$ 3200.00 |            |                       |             | N/A |                             | N/A        |             |      |
|   |  |            |            |                       |             | Yes | Surface Condition? (G/P)    | Good       |             |      |
|   |  |            |            |                       |             | No  | Curb Slope (%)              | 22.5       |             |      |

