

Intersection ID: 10033236		Main Street: OAK_LAKE_BV		Cross Street: N/A		Location:		W	
ADA ID: 891D889F9F0A		Ramp Type: PerpDiag		Initial Pass/Fail: Pass		Overall Compliance: No		Severity Score: 27.5	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
 <div>Street 1 NameOAK LAKE BV</div> <div>Stop Condition-Street 2None</div> <div>Street 2 NameENTRANCE</div> <div>Stop Condition-Street 1StopSign</div>		Possible Solutions:		Compliance		Description		Data	
		Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Grind Gutter Lip.		N/A	Ramp Length (in)	47.0	Yes	Ramp Slope (%)	6.2
				Yes	Ramp Width (in)	54.0	Yes	Ramp XSlope (%)	1.1
				N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	2.8	N/A	Flare Slope RT (%)	2.7
				N/A	Flare Traversable LT?	Yes	N/A	Flare Traversable RT?	No
				No	Landing Length (in)	N/A	Yes	DWS Provided?	Yes
				No	Landing Width (in)	N/A	Yes	DWS Contrast?	Yes
				No	Landing Slope (%)	N/A	Yes	DWS Length (in)	25.0
				No	Landing X Slope (%)	N/A	No	DWS Full Width?	No
Surveyor Notes: N/A		N/A	Landing Curb? (Y/N)	No	No	DWS Offset (in)	2.5		
		N/A	Shared Landing?	No					
		No	Gutter Ponding?	Yes	Yes	Gutter Slope (%)	1.4		
		No	Gutter Lip Ht (in)	1.0	Yes	Gutter X Slope (%)	0.2		
		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No		
			X Walk 1 Direction	To S		X Walk 2 Direction	To E		
		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A		
			X Walk 1 Slope (%)	0.2		X Walk 2 Slope (%)	0.8		
			X Walk 1 X Slope (%)	0.2		X Walk 2 X Slope (%)	1.3		
		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A		
PROW/ADA: R304.2.1, R304.2.2-Perp, R304.3.2-Para, R304.5.3, R305.1.4, R305.2, R302.7, R302.7.2			Road Slope (%)	0.6	N/A	Clear Space?	Yes		
			Road X Slope (%)	0.9	N/A	Clear Space to XWalk (in)	N/A		
		Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No		
			Obstruction Type			Storm Grate/Utility Type			
				N/A			N/A		
Total Cost:		\$	3400.00			Yes	Surface Condition? (G/P)	Good	

