

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

10.8

4.1

N/A N/A N/A N/A

N/A N/A

N/A N/A

N/A

N/A No To SE N/A

4.4

1.7

N/A

N/A N/A

N/A

N/A

Good

Intersection ID: 14835 Main Street: DISTRIBUTION ST **Cross Street: REMOUNT RD** Location: N ADA ID: 895047D034E1 Ramp Type: PerpDiag Initial Pass/Fail: Fail **Overall Compliance: No** Severity Score: 13.75

Compliance Description

Ramp Length (in)

N/A

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

59.0 No

Data Compliance Description

Ramp Slope (%)

Surface Condition? (G/P)



REMOUNT RD Street 1 Name Stop Condition-Street 2 None Street 2 Name **DISTRIBUTION ST** Stop Condition-Street 1 StopSign

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Possible Solutions:

Surveyor Notes:				
N/A				
PROW/ADA:				
Not Found, R304.2.2, R304.5.3				
Total Cost:	\$	3200.00		

	rtamp Longar (m)	00.0		rtamp Glope (70)	
Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	
N/A	Flare Type LT	N/A	N/A	Flare Type RT	
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	
	X Walk 1 Direction	To SW		X Walk 2 Direction	
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	
	X Walk 1 Slope (%)	2.9		X Walk 2 Slope (%)	
	X Walk 1 X Slope (%)	4.2		X Walk 2 X Slope (%)	
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	
	Road Slope (%)	3.3	N/A	Clear Space?	
	Road X Slope (%)	4.4	N/A	Clear Space to XWalk (in)	
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	
	Obstruction Type			Storm Grate/Utility Type	
		NI/A			





