

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

16.2

1.0

N/A

Good

Intersection ID: 45439 Main Street: HENDERSON_OAKS_DR Cross Street: HENDERSON_VALLEY_LN Location: W

ADA ID: 896863CC28EA Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 33.75

Compliance Description

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

Gutter Ponding?

Gutter Lip Ht (in)

Painted X Walk1?

X Walk 1 Direction

X Walk 1 Width (in)

X Walk 1 Slope (%)

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road Slope (%)

Road X Slope (%)

Any Obstructions?

Obstruction Type

Flare Traversable LT?

Flare Type LT

N/A

Codes/Mitigation Info/Possible Solution

Possible Solutions:

Field Measurements/Component Compliance

No

Yes

N/A

Yes

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

Clear Space?

Flare Traversable RT?

Data

48.0

47.0

N/A

No

To E

N/A

2.5

2.2

N/A

N/A

N/A

N/A

N/A



Street 1 Name HENDERSON OAKS DR
Stop Condition-Street 2 None
Street 2 Name N/A
Stop Condition-Street 1 N/A

The state of the product and the state of th	
	No
	N/A
	N/A
	N/A
	N/A
Surveyor Notes:	N/A
N/A	N/A
	N/A
	N/A
	N/A
PROW/ADA:	N/A
Not Found, R304.5.1, R304.2.2	N/A
	N/A
	N/A
	N/A

Remove & Replace Entire Ramp.





Total Cost:



N/A

1850.00