cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



| Intersection ID: 15725 | Main Street: CLANTON_RD | | | Cross Street: S_TRYON_ST | | | | Location: | SE |
|---|-------------------------|---------------------|--|--------------------------|-----------------------|--------------------|-------------------|-----------------------------|------|
| | | | | | | | | | |
| ADA ID: 89CF86AF5EF1 Ramp Type: Perp | | | Initial Pass/Fail: Fail Overall Compliance: No | | | | o Severity Score: | 26.25 | |
| Codes/Mitigation Info/Possible Solution | | | Field Measurements/Component Compliance | | | | | | |
| | · / · · · | Possible Solutions: | | Compliance Description | | Data Compliance De | | liance Description | Data |
| | mild th | Remove & Replac | e Entire Ramp. | N/A | Ramp Length (in) | 60.0 | No | Ramp Slope (%) | 12.9 |
| | 2 24 2 | - | - | Yes | Ramp Width (in) | 48.0 | No | Ramp XSlope (%) | 4.0 |
| 6. UT TIL | 6 · · · · · | | | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| 5 | HE AN | | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| CLANTON PD | 189 | | | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| A AND A | | | | N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| | 90 0 | Surveyor Notes: | | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| the second se | - | N/A | | N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| BASS | ALLEN TO | | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| | 1 To and | | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| | 1. | | | N/A | Shared Landing? | N/A | | | |
| | | PROW/ADA: | | N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| | | Not Found, R304. | 2.2, R304.5.3 | N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A |
| | and all | , | , | N/A | Painted X Walk1? | Yes | N/A | Painted X Walk2? | N/A |
| | # / | | | | X Walk 1 Direction | To W | | X Walk 2 Direction | N/A |
| | | | | N/A | X Walk 1 Width (in) | 102.0 | N/A | X Walk 2 Width (in) | N/A |
| Street 1 Name | S TRYON ST | | | | X Walk 1 Slope (%) | 2.3 | | X Walk 2 Slope (%) | N/A |
| Stop Condition-Street 2 | Signal | | | | X Walk 1 X Slope (%) | 1.1 | | X Walk 2 X Slope (%) | N/A |
| Street 2 Name | N/A | | | N/A | Ramp inside XWalk1? | Yes | N/A | Ramp inside XWalk2? | N/A |
| Stop Condition-Street 1 | N/A | | | | Road Slope (%) | N/A | N/A | Clear Space? | N/A |
| | | | | | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A |
| | | | | N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | | Total Cost: | \$ 1 | 850.00 | Obstruction Type | | | Storm Grate/Utility Type | |
| | | | | | | N/A | | | N/A |
| | | | | | | | Yes | Surface Condition? (G/P) | Good |