

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

Intersection ID: 30317 Main Street: FLYING SCOTSMAN DR **Cross Street: ROCKET LN** Location: W Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** ADA ID: 8B9AE7441852 Ramp Type: PerpDiag 8.75

**Codes/Mitigation Info/Possible Solution** 

Field Measurements/Component Compliance

Compliance Description

Data



Street 1 Name **FLYING SCOTSMAN DR** Stop Condition-Street 2 None **ROCKET LN** Street 2 Name Stop Condition-Street 1 StopSign

Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1

N/A No N/A N/A

Compliance Description

Yes Ramp Slope (%) Ramp Length (in) 50.0 7.5 Yes Ramp XSlope (%) Ramp Width (in) 42.5 1.0 N/A Flare Type LT N/A Flare Type RT N/A N/A N/A Flare Slope RT (%) N/A Flare Slope LT (%) Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A N/A **DWS Provided?** N/A Landing Length (in) Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A N/A Landing Slope (%) DWS Length (in) N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A Shared Landing? **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A Painted X Walk1? No N/A Painted X Walk2? No X Walk 1 Direction To SE X Walk 2 Direction To NE N/A X Walk 1 Width (in) X Walk 2 Width (in) N/A X Walk 1 Slope (%) 4.6 X Walk 2 Slope (%) 1.6 X Walk 1 X Slope (%) 0.8 X Walk 2 X Slope (%) 2.6 N/A N/A Ramp inside XWalk2? N/A Ramp inside XWalk1? Road Slope (%) 1.7 N/A Clear Space? N/A N/A Road X Slope (%) 3.8 Clear Space to XWalk (in) N/A N/A N/A Any Obstructions? Storm Grate/Utility Hazard? N/A **Obstruction Type** Storm Grate/Utility Type N/A N/A Yes Surface Condition? (G/P) Good





Total Cost:



3200.00