

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 30082 Main Street: VILLAGE\_SHOPPING\_CENTERCORRESINStreet: J\_W\_CLAY\_BV Location: SE

ADA ID: 8D6B51AD407A Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 21.25

## **Codes/Mitigation Info/Possible Solution**

## Field Measurements/Component Compliance



Street 1 Name VILLAGE SHOPPING CENTER DR N
Stop Condition-Street 2 Signal
Street 2 Name J W CLAY BV
Stop Condition-Street 1 Signal

Possible Solutions:

Remove & Replace Curb Ramp With
Two New Directional Ramps or
Equivalent.

Surveyor Notes:
N/A

PROW/ADA:
Not Found, R304.5.1, R304.2.2

Total Cost: \$ 3200.00

| Field Measurements/Component Compliance |                       |       |      |                             |       |
|---|-----------------------|-------|------|-----------------------------|-------|
| Compliance Description                  |                       | Data  | Comp | liance Description          | Data  |
| N/A                                     | Ramp Length (in)      | 56.0  | No   | Ramp Slope (%)              | 8.4   |
| No                                      | Ramp Width (in)       | 38.5  | Yes  | Ramp XSlope (%)             | 1.7   |
| N/A                                     | Flare Type LT         | N/A   | N/A  | Flare Type RT               | N/A   |
| N/A                                     | Flare Slope LT (%)    | N/A   | N/A  | Flare Slope RT (%)          | N/A   |
| N/A                                     | Flare Traversable LT? | N/A   | N/A  | Flare Traversable RT?       | N/A   |
| N/A                                     | Landing Length (in)   | N/A   | N/A  | DWS Provided?               | N/A   |
| N/A                                     | Landing Width (in)    | N/A   | N/A  | DWS Contrast?               | N/A   |
| N/A                                     | Landing Slope (%)     | N/A   | N/A  | DWS Length (in)             | N/A   |
| N/A                                     | Landing X Slope (%)   | N/A   | N/A  | DWS Full Width?             | N/A   |
| N/A                                     | Landing Curb? (Y/N)   | N/A   | N/A  | DWS Offset (in)             | N/A   |
| N/A                                     | Shared Landing?       | N/A   |      |                             |       |
| N/A                                     | Gutter Ponding?       | N/A   | N/A  | Gutter Slope (%)            | N/A   |
| N/A                                     | Gutter Lip Ht (in)    | 1.0   | N/A  | Gutter X Slope (%)          | N/A   |
| N/A                                     | Painted X Walk1?      | Yes   | N/A  | Painted X Walk2?            | Yes   |
|   | X Walk 1 Direction    | To N  |      | X Walk 2 Direction          | To W  |
| N/A                                     | X Walk 1 Width (in)   | 110.0 | N/A  | X Walk 2 Width (in)         | 110.0 |
|   | X Walk 1 Slope (%)    | 3.4   |      | X Walk 2 Slope (%)          | 4.3   |
|   | X Walk 1 X Slope (%)  | 4.9   |      | X Walk 2 X Slope (%)        | 0.7   |
| N/A                                     | Ramp inside XWalk1?   | Yes   | N/A  | Ramp inside XWalk2?         | Yes   |
|   | Road Slope (%)        | 3.8   | N/A  | Clear Space?                | N/A   |
|   | Road X Slope (%)      | 6.4   | N/A  | Clear Space to XWalk (in)   | N/A   |
| N/A                                     | Any Obstructions?     | N/A   | N/A  | Storm Grate/Utility Hazard? | N/A   |
|   | Obstruction Type      |       |      | Storm Grate/Utility Type    |       |
|   |                       | N/A   |      |                             | N/A   |
|   |                       |       | Yes  | Surface Condition? (G/P)    | Good  |
| -                                       |                       |       | -    |                             |       |





