

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

| Intersection ID: 11538 | Main Street: FREEDOM_DR | | | | Street: | BERRYHILL_RD | Location: | w | | |
|--|-------------------------|------------------------|--------|--|---------------------|-----------------------|--------------------|---------------------|-----------------------------|------|
| ADA ID: 8D6F6DDA97FA | Ramp Type: Perp | | | Initial Pass/Fail: Fail Overall Compliance: No | | | | | | 22.5 |
| Codes/Mitigation Info/Possible Solution | | | | Field Measurements/Component Compliance | | | | | | |
| | Possible Solutions: | | | | | | liance Description | Data | | |
| E. E. | IK/, 🔍. 💇 | Remove & Replace Entir | o Damn | | N/A | Ramp Length (in) | 69.0 | No | Ramp Slope (%) | 9.4 |
| | Part 1 | | e Ramp | • | No | Ramp Width (in) | 47.0 | Yes | Ramp XSlope (%) | 4.6 |
| | | | | | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| OCEERS OF | | | | | N/A | Flare Slope LT (%) | N/A | | Flare Slope RT (%) | N/A |
| 200 | | | | | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| | | | | | N/A | Landing Length (in) | N/A | | DWS Provided? | N/A |
| | | Surveyor Notes: | | | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| | | N/A | | | N/A | Landing Slope (%) | N/A | | DWS Length (in) | N/A |
| | | N/A | | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| | | | | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| | | | | | N/A | Shared Landing? | N/A | | | 10/4 |
| | | PROW/ADA: | | | N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| the state of the s | | 04.0.0 | | N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A | |
| 1 marsh | Not Found, R304.5.1, R3 | 04.2.2 | | N/A | Painted X Walk1? | Yes | N/A | Painted X Walk2? | N/A | |
| | | | | N/A | X Walk 1 Direction | To SE | N/A | X Walk 2 Direction | N/A N/A | |
| | | | | NU/A | | | N/A | | | |
| | | | | N/A | X Walk 1 Width (in) | 105.0 | N/A | X Walk 2 Width (in) | N/A | |
| Street 1 Name | BERRYHILL RD | | | | | X Walk 1 Slope (%) | 1.7 | | X Walk 2 Slope (%) | N/A |
| Stop Condition-Street 2 | Signal | | | | | X Walk 1 X Slope (%) | 6.2 | | X Walk 2 X Slope (%) | N/A |
| Street 2 Name | N/A | | | | N/A | Ramp inside XWalk1? | Yes | N/A | Ramp inside XWalk2? | N/A |
| Stop Condition-Street 1 | N/A | | | | | Road Slope (%) | N/A | N/A | Clear Space? | N/A |
| | | | | | | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A |
| | | | | | N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | | Total Cost: | \$ | 1850.00 | | Obstruction Type | | | Storm Grate/Utility Type | |
| | | | | | | | N/A | | | N/A |