

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A	Main St	reet: BYRUM_DR	Cross	Street:	PINEY_TOP_DR	Location:	SW			
ADA ID: 8E229711BF54	Ramp Type: Perpendicular			Initial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	22.5		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	1997	Possible Solutions:		Compliance Description Data Compliance			liance Description	Data		
III III	6/	Remove & Replace Entire Ramp).	N/A	Ramp Length (in)	120.0	No	Ramp Slope (%)	11.3	
A CARLER CONTRACTOR	1 3			No	Ramp Width (in)	36.0	No	Ramp XSlope (%)	3.7	
A STAR AND	1 3 8			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	mar 1			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
A DESCRIPTION OF THE DESCRIPTION				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
A CONTRACT OF	Mary of Mary			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	See .	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
the second se	24	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
	and the second			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
	1111			N/A	Shared Landing?	N/A				
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
AND A ALL DE	N. N. MA	R304.5.1, R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
ALLER - ALLER -					X Walk 1 Direction	To NE		X Walk 2 Direction	N/A	
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name P	PINEY TOP DR	-			X Walk 1 Slope (%)	3.0		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	3.6		X Walk 2 X Slope (%)	N/A	
Street 2 Name	. c N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A	
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	l	
						N/A			N/A	

Yes Surface Condition? (G/P)

Good

