

Access Compliance Report Public Rights-of-Way (Curb Ramps)



				. /					
Intersection ID: N/A	Main Street: JAMES_RD			Cross Street: WILLIAM_REYNOLDS_DR				Location:	NW
ADA ID: 8E40F2D9466	2 Ramp Ty	Ramp Type: Combination2Diag			ail: Fail Overall C	nce: No Severity Score:		0	
Codes/Mitigation Info/Possible Solution Field Measurements/Component Com								nent Compliance	
		Possible Solutions:		Compliance Description		Data Comp		bliance Description	Data
1 8 C . 1		Remove & Replace Curb Ra	rb Ramp With		Ramp Length LT (in)	41.5	N/A	Ramp Length RT (in)	53.0
		Two New Directional Ramps		No	Ramp Width LT (in)	47.0	Yes	Ramp Width RT (in)	48.0
		Equivalent.		Yes	Ramp Slope LT (%)	3.0	No	Ramp Slope RT (%)	9.4
Carlos and a				No	Ramp XSlope LT (%)	2.6	Yes	Ramp XSlope RT (%)	1.6
53 × 0		Surveyor Notes:		N/A	Ramp Length (in)	48.5	Yes	Ramp Slope (%)	2.6
				Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	3.9
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		PROW/ADA:		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
A CONTRACTOR	B &			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
CEL CLEVE	6. A A A A A A A A A A A A A A A A A A A			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
MARADAN	- 19 V			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
- Duran D	all your			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
333		Not Found, R304.5.1, R304.	5.3,	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
A BEAR A	The put	R304.3.2		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	The Area and the			N/A	Shared Landing?	N/A			
				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Street 1 Name None				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Stop Condition-Street 1	WILLIAM REYNOLDS DR			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
Street 2 Name	StopSign				X Walk 1 Direction	To E		X Walk 2 Direction	To S
Stop Condition-Street 2	JAMES RD				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
					X Walk 1 Slope (%)	0.6		X Walk 2 Slope (%)	1.5
					X Walk 1 X Slope (%)	1.2		X Walk 2 X Slope (%)	1.7
		Total Cost: \$	3200.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
					Road Slope (%)	2.3		Clear Space?	N/A
					Road X Slope (%)	0.9	N/A	Clear Space to XWalk (in)	N/A
							N/A	Any Obstruction?	N/A
		Alexandre and a second se		AT Ja	Rent way - Statistical			Obstruction Type	
			1.1		- and a state of the				N/A
		+ 1000 7		and the second s	And And		N/A	Storm Grate/Utility Hazard?	N/A
		+		/				Storm Grate/Utility Type	N/A
			A LI	1-					N/A

N/A Surface Condition? (G/P) Yes Good Curb Slope (%) 12.8





