

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

N/A

N/A

N/A

N/A

5.6

3.4

2.7

No

Yes

Yes

24.0

Yes

1.0

3.4

4.4

No

To W

N/A

0.7

Sloped

Intersection ID: 10014838 Main Street: THE PLAZA Cross Street: N/A SE Location:

Initial Pass/Fail: Pass **Overall Compliance: No** 0 ADA ID: 8E6DF781018B Ramp Type: Combination2Diag **Severity Score:** 

## **Codes/Mitigation Info/Possible Solution**

## Field Measurements/Component Compliance

N/A

N/A

N/A

N/A

Yes

Yes

N/A

N/A

N/A

Yes

Yes

Yes

Yes

Yes

Yes

No

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

**DWS Contrast?** 

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

Flare Traversable RT?

Ramp XSlope RT (%)

Data

51.0

60.0

6.4

1.8

25.0

48.0

7.4

No

57.0

47.0

0.6

0.3

No

No

No

0.0

No

To N

N/A

2.3

Sloped



Street 1 Name Stop Condition-Street 1 Street 2 Name Stop Condition-Street 2 Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Remove & Replace Gutter. Surveyor Notes: N/A PROW/ADA: Not Found, R304.2.1, R304.5.3

None THE PLAZA None **ENTRANCE** 

Total Cost:

Compliance Description N/A Ramp Length LT (in) Yes Ramp Width LT (in) Yes Ramp Slope LT (%) Ramp XSlope LT (%) Yes N/A Ramp Length (in) Yes Ramp Width (in) N/A Flare Type LT N/A Flare Slope LT (%) N/A Flare Traversable LT? Yes Landing Length (in) No Landing Width (in) Landing Slope (%) Yes Yes Landing X Slope (%) N/A Landing Curb? (Y/N) N/A Shared Landing? **Gutter Ponding?** Yes Yes Gutter Lip Ht (in) N/A Painted X Walk1? X Walk 1 Direction X Walk 1 Width (in) X Walk 1 Slope (%)







