

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 4810	Main Str	eet: BEN_CRAIG_DR		Cross Stree	t: MALLARD_CR	REEK_RD		Location:	N
ADA ID: 8F81C60C848C	Ramp Ty	/pe: Perpendicular		Initial Pass/I	Fail: Fail C	Overall Complia	nce: N	o Severity Score:	22.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Com	n Data	Data Compliance Description			
Contract To See		Remove & Replace Entire	Ramp.	N/A	Ramp Length (in)	61.0	No	Ramp Slope (%)	11.7
	1 1 Maria		•	No	Ramp Width (in)	46.0	No	Ramp XSlope (%)	2.7
	1 L. ASTRON			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
A0.				N/A	Flare Slope LT (%	ő) <b>N/A</b>	N/A	Flare Slope RT (%)	N/A
Ster State State				N/A	Flare Traversable	LT? N/A	N/A	Flare Traversable RT?	N/A
the stand				N/A	Landing Length (ir	n) <b>N/A</b>	N/A	DWS Provided?	N/A
The second se		Surveyor Notes:		N/A	Landing Width (in)	) <b>N/A</b>	N/A	DWS Contrast?	N/A
े है		N/A		N/A	Landing Slope (%	) <b>N/A</b>	N/A	DWS Length (in)	N/A
- Ban	3 L			N/A	Landing X Slope (	(%) N/A	N/A	DWS Full Width?	N/A
CAN CRAIG DR				N/A	Landing Curb? (Y	/N) <b>N/A</b>	N/A	DWS Offset (in)	N/A
	the second			N/A	Shared Landing?	N/A			
130 DI //		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	<u>6</u>	R304.5.1, R304.2.2, R304.	5.3	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	MACHER			N/A	Painted X Walk1?	No No	N/A	Painted X Walk2?	N/A
	5. And the second				X Walk 1 Directior	n To SW		X Walk 2 Direction	N/A
Retain and Ret , 111	M AT			N/A	X Walk 1 Width (ir	n) <b>N/A</b>	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	BEN CRAIG DR				X Walk 1 Slope (%	%) 5.5		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign				X Walk 1 X Slope	(%) 0.7		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWa	alk1? <b>N/A</b>	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	) <b>N/A</b>	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	? <b>N/A</b>	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$ 185	50.00	Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

es Surface Condition? (G/P)

Good

